5. TROUBLE DIAGNOSIS

5-1. Contents of Remote Controller Switch Alarm Display	5-1-1-1
5-1-1. U-25PZ3E5, U-36PZ3E5, U-50PZ3E5, U-60PZ3E5A, U-71PZ3E5A	
U-36PZH3E5, U-50PZH3E5, U-60PZH3E5	5-1-1-1
5-1-2. U-100PZ3E5, U-125PZ3E5, U-140PZ3E5	
U-100PZ3E8, U-125PZ3E8, U-140PZ3E8	5-1-2-1
5-1-3. U-71PZH3E5, U-100PZH3E5, U-125PZH3E5, U-140PZH3E5	0 1 2 1
U-71PZH3E8, U-100PZH3E8, U-125PZH3E8, U-140PZH3E8	5-1-3-1
5-2. PAC System Alarm Codes	
5-2-1. Indoor	
5-2-2. Outdoor	
	5-2-2-1-1
5-2-2-1. U-25PZ3E5, U-36PZ3E5, U-50PZ3E5, U-60PZ3E5A, U-71PZ3E5A	50044
U-36PZH3E5, U-50PZH3E5, U-60PZH3E5	5-2-2-1-1
5-2-2-2. U-100PZ3E5, U-125PZ3E5, U-140PZ3E5	
U-100PZ3E8, U-125PZ3E8, U-140PZ3E8	5-2-2-2-1
5-2-2-3. U-71PZH3E5, U-100PZH3E5, U-125PZH3E5, U-140PZH3E5	
U-71PZH3E8, U-100PZH3E8, U-125PZH3E8, U-140PZH3E8	5-2-2-3-1
5-3. Inspection of Parts (Outdoor Unit)	5-3-1
5-4. How to Replace Fan Motor	5-4-1
5-5. Removing Drain Pan	
5-6. Replacing nanoe unit	
5-7. How to Replace Receiver PCB of Wireless remote controller CZ-RWRY3	
5-7. How to Replace Receiver FCB of Wireless remote controller CZ-RWR13	3-7-1

5-1. Contents of Remote Controller Switch Alarm Display 5-1-1. U-25PZ3E5, U-36PZ3E5, U-50PZ3E5, U-60PZ3E5A, U-71PZ3E5A U-36PZH3E5, U-50PZH3E5, U-60PZH3E5

ON: ○ Blinking: ☆ OFF: ●

			Wired	remo	Vireles te con iver di	trolle
	Possi	ible cause of malfunction	remote control	Д -(U		*
			display	Operation	Timer	Standby
	Failure in receiving serial	Faulty remote controller				
	signal from remote controller's indoor unit	Disconnection / Contact failure of remote controller wiring			!	
	Settings of system address, indoor unit address and group control are not made	CHK(check) pins on the indoor unit control PCB are short circuited In the case of non-group control: Power supply OFF of outdoor unit Disconnection / Contact failure of indoor / outdoor control line* In the case of group control: Auto address operation was not carried out.	E01	blinki	perating lam	
	Setting failure of nonvolatile memory IC	Faulty setting of EEPROM (IC010) on indoor unit		🌣		•
	Failure in indoor unit serial	Faulty remote controller	F00			1
	signal from remote controller	Wrong wiring of remote controller	E02		1	
	Error in indoor unit receiving sid	gnal from remote controller (central)	E03	1		1
	5	Disconnection / Contact failure of indoor / outdoor control line*			-	1
		Faulty indoor unit control PCB Faulty outdoor unit control PCB Communication circuit fuse (F302) on indoor unit control PCB opened		Stan	dby	
	Failure in indoor unit receiving serial signal from outdoor unit	Fuse on outdoor unit control PCB opened Since failure of an outdoor fan motor is considered as a cause, both outdoor unit control PCB and outdoor unit fan motor are exchanged simultaneously.	E04	lamp	blinkin	ng
Serial		Setting error of indoor unit address Capacity of indoor / outdoor units is mismatched.			! ! !	
communication	Duplication of indoor unit address	Duplication of indoor unit address setting	E08			
errors Missetting	Duplication of main remote controller setting	Error because of more than one remote controller setting to main	E09		ating la	; amp
	Improper setting	Duplication of main unit in group control	E14	blinki	ng ¦	!
	Communication error between main and sub indoor units	Disconnection of wiring between main unit and additional units Contact failure of wiring Faulty indoor unit control PCB (Main or Addition)	E18	 	•	•
		The total capacity of indoor units is too low.	E15	Stan		1
	Auto address alarm	The total capacity of indoor units is too high The numbers of indoor units is too many	E16	lamp	blinkin	ng ├-;¢
	Indoor & outdoor unit type mismatched	Setting error, indoor / outdoor unit type / model mismatched	L02		 	
	Duplication of group control's main indoor unit	Duplication of main indoor unit address in group control	L03	Stan	ating a dby s blinki	
	Group control wiring is connected to individual control indoor unit	Group control wiring is connected to individual control indoor unit	L07		taneou	
	Indoor unit address is not set		L08	_ ~		~
	Indoor unit capacity is not set		L09			1
	4-way valve locked trouble / op	4-way valve locked trouble / operation failure		Stand	ating adby s blinkitaneou	ing

^{*} indoor / outdoor control line* : Connection cable between outdoor and indoor unit

Continued

			Wired	remo	Virele: te con iver di	trolle
	Pos	sible cause of malfunction	remote control		(<u></u>	*
	1.00	SIDIO GUUGO OI IIIUII UIIGIGII	display	Operation	Timer	Standby (
		Indoor unit fan motor locked		"	 -	- 00
	Indoor unit fan motor trouble	Indoor unit fan motor layer short	P01		į	
		Contact failure in thermostat protector circuit				
	Faulty wiring connections of (co	eiling) indoor unit panel	P09	1		
		Faulty drain pump		7	1 1 1	-
	Activation of floor avoitab	Drainage failure		Time	¦ er and s	¦ standh
	Activation of float switch wiring	Contact failure of float switch wiring	P10	lamp	blinkir	
	3	High water alarm for the case of Middle static pressure duct (PF) model installed vertically		alter	nately	<u> </u>
	Foultry drain numer	Faulty drain pump	D11	7	~	-
	Faulty drain pump	Drain pump locked	P11			
	Indoor unit fan motor trouble	Indoor unit fan motor locked Faulty wiring connections of indoor unit fan motor	P12			
	Valve error	Valve error Refrigerant circuit error Wrong installation for refrigerant piping and wiring	P13		1 1 1 1	
Activation of protective	Discharge temperature protective alarm Compressor discharge temperature trouble				1	
device	Activation of high pressure switch	Condensing pressure trouble	P04		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	Power supply failure	Open phase detected AC power supply trouble	P05	stand blinkir	¦ ating an	
	HIC sensor trouble	HIC(IPM) temperature trouble	P07		by lamp	
	Insufficient gas	Insufficient gas level detected	P15			1 .
	Compressor overcurrent trouble	e	P16	+		🌣
	Fan motor locked / reversed airflow detected	Outdoor unit fan motor trouble Outdoor unit fan trouble	P22			
	Inverter compressor trouble					!
	Group control trouble	Indoor unit in group control trouble	P31			
	Activation of current control compressor's protective device	Primary (input) overcurrent detected	H01		1	
	PAM trouble (overcurrent / over-voltage), Activation of compressor's protective device	PAM trouble	H02	Time	lamp b	linking
	Primary current control, Activation of compressor's protective device	Primary current CT sensor failure	H03		 	
		Indoor heat exchanger temperature sensor (E1) trouble	F01		ating ar	
	Indoor unit thermistor open / short	Indoor heat exchanger temperature sensor (E2) trouble	F02	timer lamp alternately		linking
Thermistor	opon / onort	Indoor air temperature sensor (TA) trouble	F10	* *		•
fault	Outdoor unit the armieter	Compressor discharge temperature sensor (TD) trouble	F04		ating ar	
	Outdoor unit thermistor open / short	Outdoor heat exchanger temperature sensor (C1) trouble	F06		nately	HIMIN
		Outdoor air temperature sensor (TO) trouble	F08	*	<u></u>	0
Nonvolatile me	emory failure	Indoor unit EEPROM trouble	F29	timer simu	ating ar lamp better	olinking sly

5-1-2. U-100PZ3E5, U-125PZ3E5, U-140PZ3E5 U-100PZ3E8, U-125PZ3E8, U-140PZ3E8

ON: ○ Blinking: ☆ OFF: ●

			Wired	remo	Virele te con iver di	troller
	Possi	ible cause of malfunction	E01 E04 E06 E08 E09 E14	Operation 🖳	Timer	Standby 🛞
	Failure in receiving serial	Faulty remote controller			<u> </u>	
	signal from remote controller's indoor unit	Disconnection / Contact failure of remote controller wiring				
	In the case of non-group control: Settings of system address, indoor unit address and group control are not made In the case of non-group control: • Power supply OFF of outdoor unit • Disconnection / Contact failure of indoor / outdoor control line* In the case of group control: Auto address operation was not carried out		E01	blink	ating la	amp
	Setting failure of nonvolatile memory IC	Faulty setting of EEPROM (IC010) on indoor unit		🌣	•	•
	Failure in indoor unit serial	Faulty remote controller	E02			
	signal from remote controller	Wrong wiring of remote controller			-	
	Error in indoor unit receiving sig	gnal from remote controller (central)	E03		-	1
		Disconnection / Contact failure of indoor / outdoor control line*				
		Faulty indoor unit control PCB Faulty outdoor unit control PCB Communication circuit fuse (F302) on indoor unit control PCB opened	1			
	Failure in indoor unit receiving serial signal from outdoor unit	Fuse on outdoor unit control PCB opened Since failure of an outdoor fan motor is considered as a cause, both outdoor unit control PCB(CR/HIC) and outdoor unit fan motor are exchanged simultaneously.		Stan	dby blinkir	ng
		Setting error of indoor unit addressCapacity of indoor / outdoor units is mismatched.		•	•	*
		Disconnection / Contact failure of indoor / outdoor control line*	E06			
Serial	Failure in outdoor unit receiving serial signal from indoor unit	Disconnection of indoor / outdoor control line* Communication circuit fuse (F302) on indoor unit control PCB opened				
communication errors	indoor driit	Indoor unit control PCB address setting error			į	į
Missetting	Duplication of indoor unit address Duplication of indoor unit address setting				 	1
	Duplication of main remote controller setting Error because of more than one remote controller setting to main				ating l	amp
	Improper setting	Duplication of main unit in group control	E14	blink	ing	1
	Communication error between main and sub indoor units	Disconnection of wiring between main unit and additional units Contact failure of wiring Faulty indoor unit control PCB (Main or Addition)	E18	*	•	•
		The total capacity of indoor units is too low.	E15	04		!
	Auto address alarm	The total capacity of indoor units is too high The numbers of indoor units is too many	E16	Stan	blinkir	
		No indoor unit connected	E20			🌣
	Indoor & outdoor unit type mismatched	Setting error, indoor / outdoor unit type / model mismatched	L02			1
	Duplication of group control's main indoor unit address in group control		L03	Stan		
	Group control wiring is connected to individual control indoor unit Group control wiring is connected to individual control		L07	simu	s blink Itaneo	usly
	Indoor unit address is not set		L08			*
	Indoor unit capacity is not set		L09		1	1
	Outdoor unit capacity is not set Indoor unit type setting error	or setting error	L10	Operating Standby		
	Type of indoor / outdoor units is		L13		s blink Itaneo	
	4-way valve locked trouble / op	eration failure	L18	1 24	:	1 74

 $^{^{\}star}$ indoor / outdoor control line $\!^{\star}$: Connection cable between outdoor and indoor unit

Continued

			Wired remote	remo	Virele: te con iver di	trolle splay
	Pos	sible cause of malfunction	control	Operation 🖧	Timer	Standby 🛞
		Indoor unit fan motor locked			1	
	Indoor unit fan motor trouble	Indoor unit fan motor layer short	P01		1 1 1	
		Contact failure in thermostat protector circuit				
	Faulty wiring connections of (c	eiling) indoor unit panel	P09	7	i	į
		Faulty drain pump			1 1 1	
	Activation of float switch	Drainage failure		Time	: er and s	: standb
	wiring	Contact failure of float switch wiring	P10	lamp	blinkir	
		High water alarm for the case of Middle static pressure duct (PF) model installed vertically		alter	nately	: *
	Foulty drain numan	Faulty drain pump	D44		174	*
	Faulty drain pump	Drain pump locked	- P11		1	1
	Indoor unit fan motor trouble	Indoor unit fan motor locked Faulty wiring connections of indoor unit fan motor	P12		1 1 1 1	
	Valve error	Valve error Refrigerant circuit error Wrong installation for refrigerant piping and wiring	P13		 	
Activation of	Discharge temperature protective alarm	Compressor discharge temperature trouble	P03		1 1 1	
protective device	Activation of high pressure switch	Compressor discharge pressure trouble	P04		1 1 1 1	
	Power supply failure	Open phase detected AC power supply trouble	P05		: ating an by lamp	
	Insufficient gas	Insufficient gas level detected	P15	blinki	ng alter	nately
	Compressor overcurrent troub	le	P16	 	•	*
	Fan motor locked / reversed airflow detected	Outdoor unit fan motor trouble Outdoor unit fan trouble	P22	<u> </u>	1	
	Inverter compressor trouble		P29			
	Group control trouble	P31		į	<u> </u>	
	Activation of current control compressor's protective device	Primary (input) overcurrent detected	H01		1	
	PAM trouble (overcurrent / over-voltage), Activation of compressor's protective device	PAM trouble	H02	Time	lamp b	linkin
	Primary current control, Activation of compressor's protective device	Primary current CT sensor failure	H03		 	
	HIC trouble	HIC trouble DC voltage not detected	H31			
	.	Indoor heat exchanger temperature sensor (E1) trouble	F01		ating ar	
	Indoor unit thermistor open / short	Indoor heat exchanger temperature sensor (E2) trouble	F02		nately	linking
	open / short	Indoor air temperature sensor (TA) trouble	F10	*	#	•
Thermistor fault		Compressor discharge temperature sensor (TD) trouble	F04			
iduit		Outdoor heat exchanger temperature sensor (C1) trouble	F06		ating ar lamp b	
	Outdoor unit thermistor open / short	Outdoor heat exchanger temperature sensor (C2) trouble	F07	alterr	nately	,
	opon / onort	Outdoor air temperature sensor (TO) trouble	F08)8 ×	*	0
		Compressor suction temperature sensor (TS) trouble	F12		1	
Nonvolatile me	emory failure	Indoor unit EEPROM trouble	F29	timer simu	ating ar lamp b taneou	linking sly
Nonvolatile memory failure		Outdoor unit EEPROM trouble	F31	Operating and timer lamp blink simultaneously		
				\	<u> </u>	0

5-1-3. U-71PZH3E5, U-100PZH3E5, U-125PZH3E5, U-140PZH3E5 U-71PZH3E8, U-100PZH3E8, U-125PZH3E8, U-140PZH3E8

ON: ○ Blinking: ☆ OFF: ●

			Wired	remo	Virele te con iver di	ntrolle
	Possi	ible cause of malfunction	remote control display	Operation 🗘		Standby 🛞
	Failure in receiving serial	Faulty remote controller				
	signal from remote controller's indoor unit	Disconnection / Contact failure of remote controller wiring CHK(check) pins on the indoor unit control PCB are short circuited			-	-
	Settings of system address, indoor unit address and group control are not made	In the case of non-group control: • Power supply OFF of outdoor unit • Disconnection / Contact failure of indoor / outdoor control line* In the case of group control: Auto address operation was not carried out	E01	blink	ating I	amp
	Setting failure of nonvolatile memory IC	Faulty setting of EEPROM (IC010) on indoor unit		🌣	•	
	Failure in indoor unit serial signal from remote controller	Faulty remote controller	E02			
		Wrong wiring of remote controller		-		
	Error in indoor unit receiving sig	gnal from remote controller (central)	E03			1
		Disconnection / Contact failure of indoor / outdoor control line* • Faulty indoor unit control PCB • Faulty outdoor unit control PCB				
	Failure in indoor unit receiving serial signal from outdoor unit	Communication circuit fuse (F302) on indoor unit control PCB opened Fuse on outdoor unit control PCB opened Since failure of an outdoor fan motor is considered as a cause, both outdoor unit control PCB(CR/HIC) and outdoor unit fan motor are exchanged simultaneously.	E04	Stan	dby	na
		Setting error of indoor unit address Capacity of indoor / outdoor units is mismatched.		•	•	., ≺
		Disconnection / Contact failure of indoor / outdoor control line*			1	
Serial	Failure in outdoor unit receiving serial signal from indoor unit	Disconnection of indoor / outdoor control line* Communication circuit fuse (F302) on indoor unit control PCB opened	E06			
communication errors	indoor unit	Indoor unit control PCB address setting error				
Missetting	Duplication of indoor unit address	Duplication of indoor unit address setting	E08	+	1	1
	Duplication of main remote controller setting	Error because of more than one remote controller setting to main	E09	Opei	ating I	amp
	Improper setting	Duplication of main unit in group control	E14	blink		
	Communication error between main and sub indoor units	Disconnection of wiring between main unit and additional units Contact failure of wiring Faulty indoor unit control PCB (Main or Addition)	E18	 	•	•
		The total capacity of indoor units is too low.	E15		1	
	Auto address alarm	The total capacity of indoor units is too high The numbers of indoor units is too many	E16	Stan	dby blinkir	Ť,
		No indoor unit connected	E20			🔾
	Indoor & outdoor unit type mismatched	Setting error, indoor / outdoor unit type / model mismatched	L02			-
	Duplication of group control's main indoor unit address in group control				ating a	
	Group control wiring is connected to individual control indoor unit	Group control wiring is connected to individual control indoor unit	L07		s blink Itaneo	usly
	Indoor unit address is not set		L08	*		+
	Indoor unit capacity is not set		L09	1	1	
	Outdoor unit capacity is not set	or setting error	L10		ating a	and
	Indoor unit type setting error Type of indoor / outdoor units is	s different	L13	simu	s blink Itaneo	usly
	4-way valve locked trouble / op	eration failure	L18		; 0	: 🔾

 $^{^{\}star}$ indoor / outdoor control line $\!^{\star}$: Connection cable between outdoor and indoor unit

Continued

			Wired remote	remo	Virele: te con iver di	trolle splay
	Pos	sible cause of malfunction	control	Operation	Timer	Standby
		Indoor unit fan motor locked			1	
	Indoor unit fan motor trouble	Indoor unit fan motor layer short	P01		1	-
		Contact failure in thermostat protector circuit	1		!	
	Faulty wiring connections of (c	eiling) indoor unit panel	P09	1	į	
		Faulty drain pump		1	1	
	A stimulation of the stranitals	Drainage failure	1	Time	¦ r and s	: stand
	Activation of float switch wiring	Contact failure of float switch wiring	P10	lamp	blinkin	
	9	High water alarm for the case of Middle static pressure duct (PF) model installed vertically		alteri	nately	4
	- "	Faulty drain pump	544	1	*	 *
	Faulty drain pump	Drain pump locked	- P11		į	
	Indoor unit fan motor trouble	Indoor unit fan motor locked Faulty wiring connections of indoor unit fan motor	P12			
	Valve error	Valve error Refrigerant circuit error Wrong installation for refrigerant piping and wiring	P13			
Activation of	Discharge temperature protective alarm	Compressor discharge temperature trouble	P03		1	
protective device	Activation of high pressure switch	Compressor discharge pressure trouble	P04			1
	Power supply failure	Open phase detected AC power supply trouble	P05		: ating an by lamp	
	Insufficient gas	Insufficient gas level detected	P15	blinkir	ng alter	nately
	Compressor overcurrent troub	le	P16	 	•	<u> </u>
	Fan motor locked / reversed airflow detected	Outdoor unit fan motor trouble Outdoor unit fan trouble	P22			
	Inverter compressor trouble		P29			
	Group control trouble	Indoor unit in group control trouble	P31			
	Activation of current control compressor's protective device	Primary (input) overcurrent detected	H01		 	-
	PAM trouble (overcurrent / over-voltage), Activation of compressor's protective device	PAM trouble	H02	Timer	lamp b	linkin
	Primary current control, Activation of compressor's protective device	Primary current CT sensor failure	H03		174	
	HIC trouble	uble HIC trouble DC voltage not detected			 	1
		Indoor heat exchanger temperature sensor (E1) trouble	F01		ating ar	
	Indoor unit thermistor open / short	Indoor heat exchanger temperature sensor (E2) trouble	F02	alterr	lamp b ately	iinkin
	open / short	Indoor air temperature sensor (TA) trouble	F10	*	 	•
Thermistor		Compressor discharge temperature sensor (TD) trouble	F04			1
fault		Outdoor heat exchanger temperature sensor (C1) trouble	F06		ating ar lamp b	
	Outdoor unit thermistor open / short	Outdoor heat exchanger temperature sensor (C2) trouble	F07	alterr	ately	,
	open / short	Outdoor air temperature sensor (TO) trouble	F08	*	*	0
		Compressor suction temperature sensor (TS) trouble	F12	1	1	
Nonvolatile me	emory failure	Indoor unit EEPROM trouble	F29	timer simul	ating ar lamp b taneous	linkin sly
,	,	Outdoor unit EEPROM trouble	F31	timer simul	ating ar lamp b taneou	linkin sly

5-2. PAC System Alarm Codes 5-2-1. Indoor

Alarms for indoor units

Alarm Meaning
emote Controller Reception Error
emote Controller Transmission Error
ror in Indoor Unit Receiving Signal from Remote Controller (central)
ror in Indoor Unit Receiving Signal from the Outdoor Unit
uplicate Indoor Unit Address Settings Error
ore Than One Remote Controller Set to Main Error
ain Unit duplication in Simultaneous-operation Multi Control (detected outdoor unit)
to Address Alarm (The total capacity of indoor units is too low.)
to Address Alarm (The total capacity of indoor units is too high or the total number of indoor units is o many.)
ulty Communication in Group Control Wiring
ulty Con

P09	Faulty wiring connections of (ceiling) indoor unit panel
P31	Group Control Error

Check Prior to Auto Address Setting

In the case of below, conduct this process after diagnosing the problem.

- The remote controller or the outdoor unit displays an alarm
- The "Assigning" screen appears on the LCD display for more than 10 minutes

1 Auto Address	1-1 Is the power of the indoor unit(s) and outdoor unit(s) on?			Yes	2-1
71001000	1-1	is the power of the mood unit(s) and oddoor unit(s) on:		No	Power on
2 Indoor /				Yes	3-1
outdoor wiring	2-1	Has the wiring of the indoor / outdoor been completed? Is it all connected correctly?		No	Connect the wiring correctly
3 Installation or setting	3-1	Be sure that the indoor and outdoor units are connected	Yes	3-2	
related	With correct combination written in catalog		No	Coi	rect the connection
	3-2	Is the remote control wiring connected with two indoor / outdoor combinations or more for group control?		Yes	3-3
				No	3-4
	3-3	Turn on the power of only one system and run auto address setting the auto address setting, turn on the power for the next system at while still power switched on, units whose auto address setting has of multiple systems, run the auto address setting respectively in or	and run auto address setting nave completed. (In the case		
	3-4				
4 Relocation	4-1	Be sure that the indoor and outdoor units are connected with	Yes	4-2	
and resetting	4-1	correct combination described in the catalog.		Corr	ect the connection
of address	4.0	Be sure that the detailed setting items are made at factory setting.		Yes	4-3
[U3, F3,	4-2			No	Correct the setting
K3, T3]	4-3 Run the auto address setting.				

• For information on the remote control's detailed settings, see 7-3 and 7-4.

· Factory setting

Item code	Item	Value
11	Indoor unit capacity	0
12	System address	99
13	Indoor unit address	99
14	Group control address	99

NOTE

The Item code numbers 11, 12, 13 and 14 can automatically be changed to the appropriate settings from factory settings listed above by making the auto address settings according to the connected outdoor unit capacity and the number of indoor units.

If needed to reset the settings after once changed, return all the item codes to the factory shipment-time settings. It is necessary to set the auto address settings once again.

1. Error Detection Method

It is judged an error if no self-addressed communication is sent to the remote controller in a 3-minute period.


- When a remote controller is set to sub remote controller.
- When there are nine or more indoor units in a remote control group's wiring.
- When the CHK (check pin) and / or TEST (test pin) on the indoor unit control PC board are short circuited.
- The nonvolatile memory (EEPROM) is not installed or faulty when turning on the power.
- Indoor unit control PC board error.
- Remote controller check mode.
- Malfunctions of the remote controller itself (reception circuit error).

2. Error Diagnosis


1 Auto	1-1	Is auto address setting complete?	Yes	1-2	
Address	1-1	is auto address setting complete:		1-3	
	1-2	Is there an auto address setting error (Is the outdoor unit showing	Yes		
	1 2	an alarm)?	No	2-1	
	1-3	Conduct checks prior to auto address setting.			
2 Group	2-1	Is that indoor unit under group control?	Yes	2-2	
Control	2-1	is that moon unit under group control:	No	3-1	
Wiring		Are there any indoor units with their power off in the remote	Yes	Power on	
		control group's wiring?	No	2-3	
	2-3	Are nine or more indoor units connected in one remote control	Yes	Correct the wiring	
	2 0	group's wiring?	No	2-4	
	2-4	Was the remote control group's wiring changed after auto address setting was complete? Alternatively, were group settings changed	Yes	2-5	
		in the remote control detailed settings mode?	No	3-1	
	2-5	No main unit in the remote control group's wiring? Re-execute auto ad	ldress setting.		
3 Installation	3-1	Are the CHK pin and TEST pin on the indoor unit control board short-circuited?	Yes	Remove the short	
or setting			No	3-2	
related	3-2	To the wholese femote sentremen sentrements at the missest arms	Yes	3-3	
			No	3-5	
	3-3	Disconnect the connector mentioned above on the PC board of the indoor unit control PC board, and see whether the E01 goes off after several minutes. (When doing so, if two remote controllers are	Yes	3-4	
	being used and the wireless remote controller is the main remote controller, set the other remote controller as the main.)	No	3-5		
	3-4	Replace wireless remote control parts including wiring.			
	3-5	Is the LED blinking on the indoor unit's control PC board?	Yes	3-6	
	0 0	is the LED billiking off the indoor drift's control i o bodiu:	No	3-7	
	3-6	The nonvolatile memory (EEPROM) on the indoor unit's control PC be installed, improperly installed or the nonvolatile memory is faulty. Corresplacing the nonvolatile memory, write model data to it in the remote settings mode.	ect th	nis or after	
			Yes	Correct the wiring	
	3-7	Is there a short, miswiring, disconnection, wrong contact or grounding in the remote control's wiring?	No	Replace the indoor unit's control board.	

- · Regarding the remote controller check, refer to the Reference Materials.
- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit and / or replacing the indoor unit's control board, refer to the manual that is packaged with the indoor unit service board.


■ ACXA73-3129* : 4-Way Cassette Type Indoor Unit Control Board



■ ACXA73-3440* : Middle Static Pressure Duct Type Indoor Unit Control Board



■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E02 Remote Controller Transmission Error

1. Error Detection Method

When the remote controller itself cannot transmit. Or when it cannot receive the signal it transmitted itself, or when they are different and judged an error.

• Malfunction of the remote controller itself (transmit circuit error).

2. Error Diagnosis

1 Remote	1-1	Is the indoor unit under group control?	Yes	1-2
Control	1-1	to the macor and ander group control.	No	2-1
Group	1-2		Yes	Correct the wiring
Wiring	1-2		No	2-1
2 Group	2-1	Is the wireless remote controller connected to on the indoor unit's control PC board?	Yes	2-2
Control	2-1		No	2-4
Wiring	2-2	several minutes. (When doing so, if two remote controllers are	Yes	2-3
			No	2-4
	2-3	Replace wireless remote control parts including wiring.		
			Yes	Correct the wiring
	2-4	Is there a short, miswiring, open, wrong contact or grounding in the remote control's wiring?	No	Replace the indoor unit's control PC board

- Regarding the remote controller check, refer to the Reference Materials.
- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit and / or replacing the indoor unit's control board, refer to the manual that is packaged with the indoor unit service board.

E03 Error in Indoor Unit Receiving Signal from Remote Controller (central)

(When indoor unit(s) are connected)

1. Error Detection Method


It is judged an error when there is no communication from any remote controller (collectively) in a 3-minute period or if there is no communication from the central device in a 15-minute period.


- When there was once communication, but during use the remote control wiring is opened or miswired.
- The line to the central control unit for indoor / outdoor operations is opened.
- Settings are made only for sub remote controller.
- The power to the central control unit is not on and remote controllers are not being used (or the inter-unit control wiring to the central control unit is opened).
- When remote controller are not being used, only the sub remote controller is set up.

2. Error Diagnosis

1 Central	1-1	Is the central control unit connected?	Yes	1-2	
control unit	1-1	is the central control unit connected?	No	2-1	
	1-2	Is the central control unit's powered off?	Yes	Power on	
	1-2	Is the central control unit's powered on:	No	1-3	
	1-3	Are all the Main / Sub switches on the connected central control unit	Yes	1-4	
	1-5	set to Sub?	No	1-5	
	1-4	Of the central control units that are connected, set only the uppermost Main and the others to Sub. The order from top to bottom is communic \rightarrow system controller \rightarrow ON / OFF controller.			
	1-5	Is the inter-unit control wiring connected to the central control unit	Yes	Correct the setting	
	1-5	opened?	No	2-1	
2 Remote	2-1	Is the indoor unit under group control?	Yes	2-2	
controller			No	3-1	
	2-2		Yes	Correct the setting	
			No	3-1	
3 Indoor	3-1	Is the wireless remote controller connected to on the indoor unit's	Yes	3-2	
unit	3-1	control PC board?	No	3-4	
PC board	3-2	Disconnect the connector mentioned above on the control PC board of the indoor unit control PC board, and see whether the E03 goes off after several minutes. (When doing so, if two remote controllers are	Yes	3-3	
	3-2	being used and the wireless remote controller is the main remote controller, set the other remote controller as the main.)	No	3-4	
	3-3	Replace wireless remote control parts including wiring.			
			Yes	Correct the wiring	
	3-4	Is there a short, miswiring, open, wrong contact or grounding in the remote control's wiring?	No	Replace the indoor unit control board	


- Regarding the remote controller check, refer to the Reference Materials.
- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit and / or
 replacing the indoor unit's control board, refer to the manual that is packaged with the indoor unit service board.






- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit, refer to the manual that is packaged with the indoor unit service board.
- For information on the remote control's detailed settings, see 7-3 and 7-4.
- The alarm also occurs when the indoor unit cannot be recognized (indoor unit only blackout, disconnection of indoor / outdoor control line*, etc.) during auto address setting.

■ ACXA73-3129*: 4-Way Cassette Type Indoor Unit Control Board




■ ACXA73-3440*: Middle Static Pressure Duct Type Indoor Unit Control Board



^{*} indoor / outdoor control line* : Connection cable between outdoor and indoor unit

■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E04 Error in Indoor Unit Receiving Signal from the Outdoor unit

1. Error Detection Method

When there is no communication within a 3-minute period from the outdoor unit. Or, judged an error when no reply comes from the outdoor unit.

- The outdoor unit is not turned on.
- When the power was turned on after auto address setting was completed, the number of indoor units had been changed.
- Forgot to turn on the indoor unit.
- The CHK pin and / or TEST pin on the indoor unit's control PC board are shorted.
- Forgot to install the nonvolatile memory (EEPROM) when replacing the indoor unit control PC board.
- Mistakenly set the indoor unit address to Not Set in the remote control's detailed setting mode.
- · When indoor unit addresses are duplicated.
- There is a short, open, wrong contact or grounding of the indoor / outdoor control line*.
- There is an error in the receiving circuit on the signal output PC board (optional control PC board).
- · Malfunctions of the outdoor unit
- The thermistor inside the indoor unit is grounded.
- The capacity setting is mismatched between indoor units and the outdoor unit.

2. Error Diagnosis


1 Power Source	1-1	1 Is / was the power to the outdoor unit cut off?			r turning the power wait three minutes
Occirco	1-1	137 was the power to the outdoor unit out on:		1-2	wait times minutes
	4.0	le the indeed with necessary of \$2		Yes	Power on
	1-2	Is the indoor unit powered off?		No	2-1
2 Indoor /				Yes	3-1
outdoor wiring	2-1	Is the indoor / outdoor wiring connected correctly?		No	Correct the wiring
3 Number	3-1	Was the number of indoor units increased or decreased after		Yes	
and setting of indoor		auto address setting was complete?		No	3-3
units	3-2	Conduct checks prior to auto address setting.			
		Check the indoor unit addresses from the remote control's	control's	Yes	3-2
	3-3	detailed settings mode. Is it Not Set (99), or is the indoor unit's address duplicated?		No	3-4
		Check the indoor unit capacity from the remote control's detailed settings mode. Does it match the capacity of outdoor unit?		Yes	4-1
	3-4			No	3-2
4 Indoor	4-1	Are the CHK pin and / or TEST pin on the indoor unit control PC board short-circuited?	Yes	Remove the short	
unit			No	4-2	
control PC board			Yes		
1 0 board	4-2	control PC board?		No	4-5
	4-3	Disconnect the connector mentioned above on the control PC of the indoor unit control PC board, and see whether the E04 gafter several minutes. (When doing so, if two remote controllers	s off	Yes	4-4
	4-3	being used and the wireless remote controller is the main remote controller, set the other remote controller as the main.)		No	4-5
	4-4	Replace wireless remote control parts including wiring.			
	4-5	Is the LED on the indoor unit control PC board blinking?		Yes	
		13 the LED on the indoor drift control i C board blinking:		No	4-7
	4-6	The nonvolatile memory (EEPROM) on the indoor unit's control PC be improperly installed or the nonvolatile memory is faulty. Correct this control details nonvolatile memory, write model data to it in the remote control details.		r after replacing the	
	4-7				or unit control board unit control board

^{*} indoor / outdoor control line* : Connection cable between outdoor and indoor unit


- · Regarding the remote controller check, refer to the Reference Materials.
- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit and / or replacing the indoor unit's control board, refer to the manual that is packaged with the indoor unit service board.

Indoor Unit Control PCB


■ ACXA73-3129*: 4-Way Cassette Type Indoor Unit Control Board



■ ACXA73-3440*: Middle Static Pressure Duct Type Indoor Unit Control Board



■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E08 Duplicate Indoor Unit Address Settings Error

1. Error Detection Method

It is judged an error if the addresses of indoor units are duplicated.


- The indoor unit address settings are duplicated in the remote control detailed settings mode.
- The multiple unit DISP pin is shorted across the indoor unit whose address is Not Set.

2. Error Diagnosis

1 Indoor unit	1-1	\mid Is the DISP pin on the indoor unit control PC board shorted? $\qquad \vdash$	Yes	Remove the short
			No	1-2
control PC board	1-2	Conduct checks prior to auto address setting.	Yes	1-3
T o source	1-2	Does E08 fail to go off even after running auto address setting again?	No	1-4
	1-3	The nonvolatile memory (EEPROM) on the indoor unit board has failed Replace the EEPROM.	d.	
	1-4	Do not make changes to indoor unit addresses with the detailed setting controller. Make them in the remote control address change mode.	gs of	the remote

- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit, refer to the manual that is packaged with the indoor unit service board.
 - For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit, refer to the manual that is packaged with the indoor unit service board.
 - For information on the remote control's detailed settings, see 7-3 and 7-4.
 - The alarm also occurs when the indoor unit cannot be recognized (indoor unit only blackout, disconnection of indoor / outdoor control line*, etc.) during auto address setting.
 - * indoor / outdoor control line*: Connection cable between outdoor and indoor unit


■ ACXA73-3129*: 4-Way Cassette Type Indoor Unit Control Board



■ ACXA73-3440*: Middle Static Pressure Duct Type Indoor Unit Control Board



■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E09 More Than One Remote Controller Set to Main Error

1. Error Detection Method

It is judged an error when more than one remote controller in a remote control group is set as the main remote controller.

- Forgot to set one remote controller to sub in a 2-remote control group.
- When using one wireless and one wired remote controller in a control group, forgot to set one of them to sub.

2. Error Diagnosis

1 Remote controller	1-1	Set one of the 2 remote controllers to sub.
---------------------	-----	---

· Method for setting a remote controller to sub

<CZ-RTC6 series>


- (1) Press and hold the , and for 4 seconds or more simultaneously.
- (2) Select "RC. setting mode".



(3) Select the "Code no." and "Set data".



(Repeat)





CZ-RTC6 series

Code no.	Item	Set	data
Code no.	пеш	0000	0001
01	Main/Sub	Sub	Main

(4) Press **=** .

· After selecting "YES", the unit restarts.

<CZ-RTC5B>


- 1. Press and hold + + + buttons for 4 seconds or more simultaneously.
- 2. Press 🔻 / 🔼 buttons to select the "3. RC. setting mode" and press the 🖃 button.
- 3. The Code no. "01" and the Set data "0001" or the like on the remote controller's display.
- 4. Press ▼ / ▲ buttons to select the Code no. to "01" and press the ▶ button.
- 5. Press 🔻 / 📤 buttons to select the Set data to "0000" (0000: Sub 0001: Main) and press the 🖃 button.
- 6. Press button. After selecting [YES], the unit restarts.

<CZ-RTC4>

- 1. Press and hold ⊕ ★○ ★ + SET buttons for several seconds simultaneously.
- 2. This will display **SETTING**, the CODE No. "01" and the SET DATA "0001" or the like on the remote controller's display.
- 3. Press ▽/ △ buttons to select the CODE No. to "01".
- 4. Press DATA to "0000". (0000: Sub 0001: Main)
- 5. Press SET button (Once the display changes from flashing to steady, the setting is complete).
- 6. Once you press \bigcirc button, the remote controller returns to its normal display.

Wireless remote controller

CZ-RWRC3




Main / Sub setting


- Use this to set Main / Sub for the remote controller and the receiver.
- Set one to [Main] and the other to [Sub].
- Factory default: [Main]
- It is recommended to set the wired remote controller to [Main].

Main / Sub	MAIN	SUB
Main / Sub switch position	1 2 3 4	1 2 3 4

CZ-RWRU3, CZ-RWRU3W




CZ-RWRT3



* When using the infrared remote controller and the wired remote controller in combination, set the wired remote controller to [Main].

CZ-RWRY3




* When using the receiver and wired remote controller in combination, set the receiver to [Sub].

Wall Mounted Type

<When Using Wireless Remote Controller Instead of Wired Remote Controller>
When the wireless remote controller is to be used, slide the switch (SW502) to the ON position.

 If this setting is not made, an alarm will occur (The operation lamp on the display blinks.)
 See "8-3-2-1. <Optional parts setting and wiring>".



E14 Main Unit duplication in Simultaneous-operation Multi Control (detected outdoor unit)

1. Error Detection Method

It is judged an error that the main units are duplicated in the indoor unit group.

• Main unit setting was made in the indoor unit group control setting of the remote control detailed settings mode.

2. Failure Diagnosis

1 Group Control	1-1	-1 Are multiple indoor units set up as the main unit?	Yes	2-1
Address	1-1		No	2-2
2 Installation	2-1	Set up only one indoor unit as the main unit and other indoor units to t	he s	ub-unit.
& Setting	2-2	Carry out the auto address setting.		

E15 Auto Address Alarm (The total capacity of indoor units is too low.)

1. Error Detection Method

Connecting indoor unit

It is judged an error the total capacity of indoor units replied by communication is lower than that of outdoor unit.

- · The total capacity of indoor units is lower than that of outdoor unit.
- Some indoor unit(s) are connected but power is not turned on.
- The CHK pin (CN062 / CN071) and / or TEST pin (CN064) of the indoor unit is shorted when its power is turned on.

2. Error Diagnosis

1 Power	1-1	Is the indoor unit powered off?	Yes	Power on	
Source	1-1	is the indoor drift powered on:	No	2-1	
2 Indoor / outdoor	2-1	Is the indoor / outdoor wiring connected correctly?	Yes	3-1	
wiring	_ '	is the indeer / editeor wining connected correctly:	No	Correct the wiring	
3 Number of	3-1	Was the number of indoor units changed after auto address setting	Yes	3-2	
Indoor	3-1	finished?	No	4-1	
Units	3-2	Conduct checks prior to auto address setting.			
4 Indoor		Be sure that the detailed setting items are made at factory setting. [U3, F3, K3, T3]	Yes	4-2	
unit control	4-1		No	Correct the setting Run the auto address	
PC board	4-2		Yes	Remove the short	
			No	4-3	
	4-3		Yes	4-4	
			No	4-6	
		Disconnect the connector mentioned above on the control PC board of the indoor unit control PC board and see whether the E15 goes off after several minutes. (When doing so, if two remote controllers are	Yes	4-5	
		being used and the univeless remarks controller in the major remarks	No	4-6	
	4-5	Replace wireless remote control parts including wiring.			
	4-6	le the LED blinking on the indeer unit's central DC beard?	Yes	4-7	
	4-0	Is the LED blinking on the indoor unit's control PC board?	No	5-1	
	4-7	The nonvolatile memory (EEPROM) on the indoor unit's control board improperly installed or the nonvolatile memory is faulty. Correct this or nonvolatile memory, write model data to it in the remote control details	afte	replacing the	
5 Outdoor unit control PC board	5-1	Check all items under the section "Check Prior to Auto Address Setting".			

· Factory setting

Item code	Item	Value
11	Indoor unit capacity	0
12	System address	99
13	Indoor unit address	99
14	Group control address	99


NOTE

The Item code numbers 11, 12, 13 and 14 can automatically be changed to the appropriate settings from factory settings listed above by making the auto address settings according to the connected outdoor unit capacity and the number of indoor units.


If needed to reset the settings after once changed, return all the item codes to the factory shipment-time settings. It is necessary to set the auto address settings once again.

- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit, refer to the manual that is packaged with the indoor unit service board.
- For information on the remote control's detailed settings, see 7-3 and 7-4.
- The alarm also occurs when the indoor unit cannot be recognized (indoor unit only blackout, disconnection of indoor / outdoor control line*, etc.) during auto address setting.
 - * indoor / outdoor control line* : Connection cable between outdoor and indoor unit


■ ACXA73-3129* : 4-Way Cassette Type Indoor Unit Control Board



■ ACXA73-3440*: Middle Static Pressure Duct Type Indoor Unit Control Board



■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E16 Auto Address Alarm (The total capacity of indoor units is too high.)

1. Error Detection Method

It is judged an error the total capacity of indoor units is too high or the total number of indoor units is too many.

- The total capacity of indoor units is too high.
- The total number of indoor units is too many.
- When making group control of the different refrigerant system, the steps to turn on the systems one at a time have not been performed.

2. Error Diagnosis

1 Auto Address	1-1	Conduct checks prior to auto address setting.
1	1	

E18 Faulty Communication in Group Control Wiring

1. Error Detection Method

When the main remote controller cannot communicate with a sub remote controller in the remote control group. It is judged an error if a sub remote controller in a remote control group fails to communicate with the main remote controller for a period of three minutes.


- An indoor unit within the control group does not have its power on.
- The CHK pin and TEXT pin on the indoor unit in the control group are shorted.
- The DISP pin of an indoor unit sub remote controller in the control group is shorted.
- · Remote control group wiring is opened.
- More than one indoor unit in the control group is set to Main.
- An indoor unit in the control group is set to Separate.

2. Error Diagnosis


1 Indoor Unit	1-1	Is the indoor unit powered off?	Yes	Power on			
			No	1-2			
	1-2	7 to the erit pin, 1201 pin and Bier pin on the indeer drift control	Yes	Remove the short			
	1-2		No	2-1			
2 Substitute	2.1	le the remete central group's wiring append?	Yes	Correct the wiring			
Sub	2-1	Is the remote control group's wiring opened?	No	2-2			
Remote Controller	2-2	detailed settings mode. Is the main remote controller (1) set to more	Yes	2-3			
			No	3-1			
	2-3	is the mining of the remote sential group mines asserting to the	Yes	2-4			
			No	2-5			
	2-4	Run the auto address setting again.					
	2-5	Run the auto address setting again after correcting the wiring of the re	mote	e control group.			
3 Indoor	3-1	control PC board? Disconnect the connector mentioned above on the control PC board of the indoor unit control PC board, and see whether the E18 goes off	Yes	3-2			
unit			No	3-4			
control PCB			Yes	3-3			
	5-2	being used and the wireless remote controller is the main remote controller, set the other remote controller as the main.)	No	3-4			
	3-3	Replace wireless remote control parts including wiring.					
	3-4	Replace the indoor unit control PC board.					

- For information on the remote control's detailed settings, see 7-3 and 7-4.
- For information on the procedures for replacing the Indoor unit control PCB, refer to the manual that is packaged with the indoor unit service board.


■ ACXA73-3129* : 4-Way Cassette Type Indoor Unit Control Board



■ ACXA73-3440* : Middle Static Pressure Duct Type Indoor Unit Control Board



■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board




TEST pin DISP pin CHK pin RC EEPROM OPTION

P09 Error description: Indoor unit ceiling cassette air swing motor do not operate


Error was judged as no connection between the ceiling cassette panel into Indoor PCB communication (feedback signal).

Possible Causes

1. Indoor unit ceiling cassette panel connector was not properly / wrongly connected into the PCB connector



- 2. Air swing motor (inside the panel) was locked (jammed) or no operation
 - => Check the air swing motor shaft can be rotate with hand
- 3. Air swing motor (inside the panel) wiring connector loosen or wire broken
 - => Check the air swing motor wire connector connection




4. Indoor PCB for air swing control was malfunction

=> Check with multi meter at pin 1(red)-2, 1-3, 1-4 & 1-5 : 12Vdc

=> Check with multi meter at pin 6 (red)-7, 6-8, 6-9 & 6-10 : 12Vdc => Check with multi meter at pin 11 (red)-12, 11-13, 11-14 & 1 1-15 : 12Vdc

=> Check with multi meter at pin 16 (red)-17, 16-18, 16-19 & 1 6-20 : 12Vdc



P31 Group Control Error

1. Error Detection Method

• Other indoor unit alarms within the group.

1 Other indoor		Survey the indoor unit that alarms other than "P31" in the indoor unit group and specify the
unit		causes of failure.

5-2-2. Outdoor

5-2-2-1. U-25PZ3E5, U-36PZ3E5, U-50PZ3E5, U-60PZ3E5A, U-71PZ3E5A U-36PZH3E5, U-50PZH3E5, U-60PZH3E5

Alarms for outdoor units

Alarm Code	Alarm Meaning					
E04	Error in Indoor Unit Receiving Signal from the Outdoor Unit					
F04	F04 Compressor Discharge Temperature Sensor (TD) Trouble					
F06	Inlet Temperature Sensor (C1) in Heat Exchanger Trouble					
F08	Outdoor Air Temperature Sensor (TO) Trouble					
H01	Primary (input) Overcurrent Detected					
H02	PAM Trouble					
H03	Primary Current CT Sensor (current sensor) Failure					
L18	4-Way Valve Operation Failure					
P03	Compressor Discharge Temperature Trouble					
P04	High Pressure Trouble					
P05	AC Power Supply Trouble					
P07	HIC (IPM) Temperature Trouble					
P13	Alarm Valve Open					
P15	Insufficient Gas Level Detected					
P16	Compressor Overcurrent Trouble					
P22	Outdoor Unit Fan Motor Trouble					
P29	Lack of INV compressor wiring, INV compressor actuation failure (including locked), DCCT failure					

Error Codes Table

Diagnosis display	Abnormality / Protection control	Abnormality Judgment	Protection Operation	Problem	Check location
E04	Indoor / outdoor abnormal communication	After operation for 1 minute	Indoor fan only operation can start by entering into force cooling operation	Indoor / outdoor communication not establish	Indoor / outdoor wire terminal Indoor / outdoor PCB Indoor / outdoor connection wire
F04	Compressor temperature sensor abnormality	Continuous for 5s	_	Compressor temperature sensor open or short circuit	Compressor temperature sensor lead wire and connector
F06 Outdoor heat exchanger temperature sensor 1 abnormality		Continuous for 5s	_	Outdoor heat exchanger temperature sensor 1 open or short circuit	Outdoor heat exchanger temperature sensor 1 lead wire and connector
F08	Outdoor air temperature sensor abnormality	Continuous for 5s	_	Outdoor air temperature sensor open or short circuit	Outdoor air temperature sensor lead wire and connector
H01	Indoor high pressure protection	_	_	Indoor high pressure protection (Heating)	Check indoor heat exchangerAir filter dirtyAir circulation short circuit
H02	Power factor correction (PFC) circuit protection	4 times happen within 20 minutes	_	Power factor correction circuit abnormal	Outdoor PCB faulty
H03	Outdoor current transformer (CT) abnormality	_	_	Current transformer faulty or compressor faulty	Outdoor PCB faulty or compressor faulty
L18	4-way valve switching abnormality	4 times happen within 30 minutes	_	4-way valve switching abnormal	4-way valve Lead wire and connector
P03	Compressor overheating protection	4 times happen within 20 minutes	_	Compressor overheat	Insufficient refrigerant
P04	Outdoor cooling high pressure protection	4 times happen within 20 minutes	_	Cooling high pressure protection	Check refrigeration system Outdoor air circuit
P05	Indoor / outdoor misconnection abnormality	I	_	Indoor and outdoor rated voltage different	Indoor and outdoor units check
P07	Power transistor module overheating protection	4 times happen within 30 minutes	_	Power transistor module overheat	PCB faulty Outdoor air circuit (fan motor)
P15	Refrigeration cycle abnormality	2 times happen within 20 minutes	_	Refrigeration cycle abnormal	 Insufficient refrigerant or valve close
P16	Outdoor direct current (DC) peak detection	Continuous happen for 7 times	_	Power transistor module current protection	Power transistor module faulty or compressor lock
P22	Outdoor fan motor mechanism lock	2 times happen within 20 minutes	_	Outdoor fan motor lock or feedback abnormal	Outdoor fan motor lead wire and connector Fan motor lock or block
P29	Compressor abnormal revolution	4 times happen within 20 minutes	_	Compressor abnormal revolution	Power transistor module faulty or compressor lock

E04 Indoor / Outdoor Abnormal Communication


Malfunction Decision Conditions

• During startup and operation of cooling and heating, the data received from outdoor unit in indoor unit signal transmission is checked whether it is normal.

Malfunction Caused

- Faulty indoor unit PCB.
- · Faulty outdoor unit PCB.
- Indoor unit-outdoor unit signal transmission error due to wiring error.
- Indoor unit-outdoor unit signal transmission error due to breaking of wire in the connection wires between the indoor and outdoor units.


Troubleshooting




- Regarding the remote controller check, refer to the Reference Materials.
- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit and / or replacing the indoor unit's control board, refer to the manual that is packaged with the indoor unit service board.

Indoor Unit Control PCB


■ ACXA73-3129*: 4-Way Cassette Type Indoor Unit Control Board



■ ACXA73-3440*: Middle Static Pressure Duct Type Indoor Unit Control Board



■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION


F04 Compressor Temperature Sensor Abnormality


Malfunction Decision Conditions

• During startup and operation of cooling and heating, the temperatures detected by the outdoor compressor temperature sensor are used to determine sensor errors.

Malfunction Caused

- · Faulty connector connection.
- Faulty sensor.
- · Faulty PCB.






F06 Outdoor Pipe Temperature Sensor Abnormality


Malfunction Decision Conditions

• During startup and operation of cooling and heating, the temperatures detected by the outdoor pipe temperature sensor are used to determine sensor errors.

Malfunction Caused

- · Faulty connector connection.
- Faulty sensor.
- · Faulty PCB.






F08 Outdoor Air Temperature Sensor Abnormality


Malfunction Decision Conditions

• During startup and operation of cooling and heating, the temperatures detected by the outdoor air temperature sensor are used to determine sensor errors.

Malfunction Caused

- Faulty connector connection.
- Faulty sensor.
- Faulty PCB.






H01 Error Code Stored in Memory and no alarm is triggered / no TIMER LED flashing

Malfunction Decision Conditions

- Indoor high pressure is detected when indoor heat exchanger is detecting very high temperature when the unit is operating in heating operation.
- · Phenomena: unit is stopping and re-starting very often in heating mode

Malfunction Caused

- Indoor heat exchanger thermistor
- Clogged air filter or heat exchanger
- Over-bent pipe (liquid side)




H02 Power Factor Correction Protection

Malfunction Decision Conditions

- To maintain DC voltage level supply to power transistor.
- To detect high DC voltage level after rectification.

Malfunction Caused

- During startup and operation of cooling and heating, when Power Factor Correction (PFC) protection circuitry at the outdoor unit main PCB senses abnormal DC voltage level for power transistors.
- When DC voltage detected is LOW, transistor switching will turn ON by controller to push-up the DC level.
- When DC voltage detected is HIGH (391Vdc 425Vdc), active LOW signal will send by the controller to turn OFF relay RY-C.




H03 Outdoor Current Transformer

Malfunction Decision Conditions

• An input current, detected by Current Transformer CT, is below threshold value when the compressor is operating at certain frequency value for 3 minutes.

Malfunction Caused

- Lack of gas
- Broken CT (current transformer)
- Broken Outdoor PCB




L18 4-way Valve Switching Failure

Malfunction Decision Conditions

 When indoor heat exchanger is cold during heating (except deice) or when indoor heat exchanger is hot during cooling and compressor operating, the 4-way valve is detected as malfunction.

Malfunction Caused

- Indoor heat exchanger (pipe) thermistor
- · 4-way valve malfunction



^{*} Check gas side pipe - for hot gas flow in cooling mode


P03 Compressor Overheating

Malfunction Decision Conditions

• During operation of cooling and heating, when compressor tank temperature data (103°C) is detected by the compressor tank temperature sensor.

Malfunction Caused

- · Faulty compressor tank temperature sensor
- 2 / 3 way valve closed
- Refrigerant shortage (refrigerant leakage)
- · Faulty outdoor unit PCB
- · Faulty compressor




P04 Outdoor High Pressure Protection: Cooling or Soft Dry

Malfunction Decision Conditions

• During operation of cooling or soft dry, when outdoor unit heat exchanger high temperature data is detected by the outdoor unit heat exchanger thermistor.

Malfunction Caused

- Outdoor heat exchanger temperature rise due to short-circuit of hot discharge air flow.
- Outdoor heat exchanger temperature rise due to defective of outdoor fan motor.
- Outdoor heat exchange temperature rise due to defective outdoor heat exchanger thermistor.
- Outdoor heat exchanger temperature rise due to defective of outdoor unit PCB.




P05 Unspecified Voltage between Indoor and Outdoor

Malfunction Decision Conditions

• The supply power is detected for its requirement by the indoor / outdoor transmission.

Malfunction Caused

- · Wrong models interconnected.
- · Wrong indoor unit and outdoor unit PCBs used.
- · Indoor unit or outdoor unit PCB defective.




P15 Refrigeration Cycle Abnormality

Malfunction Decision Conditions

• The input current is low while the compressor is running at higher than the setting frequency.

Malfunction Caused

- · Lack of gas.
- 3-way valve close.




P16 DC Peak Detection

Malfunction Decision Conditions

During startup and operation of cooling and heating, when inverter DC peak data is received by the outdoor internal DC Peak sensing circuitry.

Malfunction Caused

- DC current peak due to compressor failure.
- DC current peak due to defective power transistor(s).
- DC current peak due to defective outdoor unit PCB.
- DC current peak due to short circuit.




P22 Outdoor Fan Motor - DC Motor Mechanism Locked

Malfunction Decision Conditions

• The rotation speed detected by the Hall IC during fan motor operation is used to determine abnormal fan motor.

Malfunction Caused

- Operation stops due to short circuit inside the fan motor winding.
- Operation stops due to breaking of wire inside the fan motor.
- Operation stops due to breaking of fan motor lead wires.
- · Operation stops due to Hall IC malfunction.
- Operation error due to faulty outdoor unit PCB.




P29 Compressor Rotation Failure

Malfunction Decision Conditions

• A compressor rotation failure is detected by checking the compressor running condition through the position detection circuit.

Malfunction Caused

- · Compressor terminal disconnect
- Faulty Outdoor PCB
- · Faulty compressor



5-2-2-2. U-100PZ3E5, U-125PZ3E5, U-140PZ3E5 U-100PZ3E8, U-125PZ3E8, U-140PZ3E8

Alarms for outdoor units

Alarm Code	Alarm Meaning
E04	Error in Indoor Unit Receiving Signal from the Outdoor Unit
E06	Outdoor Unit Failed to Receive Serial Communication Signals from Indoor Unit
E15	Auto Address Alarm (The total capacity of indoor units is too low.)
E16	Auto Address Alarm (The total capacity of indoor units is too high or the total number of indoor units is too many.)
E20	Connection Problem of Indoor / Outdoor Units.

F04	Compressor Discharge Temperature Sensor (TD) Trouble
F06	Inlet Temperature Sensor (C1) in Heat Exchanger Trouble
F07	Intermediate Temperature Sensor (C2) in Heat Exchanger Trouble
F08	Outdoor Air Temperature Sensor (TO) Trouble
F12	Compressor Inlet Suction Temperature Sensor (TS) Trouble
F31	Outdoor Unit Nonvolatile Memory (EEPROM) Trouble

H01	Primary (input) Overcurrent Detected
H02	PAM Trouble
H03	Primary Current CT Sensor (current sensor) Failure
H31	HIC Trouble

L10	Outdoor Unit Capacity not Set or Invalid
L13	Indoor Unit Type Setting Error
L18	4-Way Valve Operation Failure

P03	Compressor Discharge Temperature Trouble
P04	High Pressure Trouble
P05	AC Power Supply Trouble
P13	Alarm Valve Open
P15	Insufficient Gas Level Detected
P16	Compressor Overcurrent Trouble
P22	Outdoor Unit Fan Motor Trouble
P29	Lack of INV compressor wiring, INV compressor actuation failure (including locked), DCCT failure
P31	Group Control Error

Symptoms and Parts to Inspect

Remote controller alarm display	Alarm contents	Judgement conditions	Eliminating condition of alarm	Judgement and correction
P03	Abnormal discharge temperature error • Discharge temp. detected at or above the specified value	Stops when temp. exceeds 103°C. Alarm output on 5 pre-trips	Recovery at restart	Check refrigerant cycle (gas leak). Trouble with electronic expansion valve Check discharge temperature sensor (TD).
P05	CT disconnected or AC power supply error DC voltage charge failure	The current value transmitted from the microcomputer on the outdoor unit control substrate is low. When no AC power input for more than 30 seconds to 5 minutes: Single alarm	Recovery at restart	 Check outdoor unit control PCB. Lack of reactor wire Check power frequency.
P15	Insufficient gas level detected.	 Discharge temperature is 95°C or higher. Electronic expansion valve is at Step 480. When the above has continued for 1 minute. Indoor air sucking due to body thermostat max (E1 or E2) - TA ≤ 4°C Secondary current ≤ Current value of gas shortage determination 	Recovery at restart	1.Check refrigerant cycle (gas leak). 2.Trouble with electronic expansion valve 3.Check outdoor unit valve opening.
L18	4-way valve operation failure • Judged after heating operating for 5 minutes consecutively.	The indoor unit heat exchanger temperature drops even though the compressor is switched on during the heating mode: To +20°C ≤ C1 Pre-trip 1 time	Recovery at restart	Check 4-way valve. Check 4-way valve wiring. Check outdoor unit control PCB.
P04	High-pressure protection error	High pressure switched ON → OFF (Alarm is output when switch opened.) Pre-trip 4 times.	Recovery at restart	Overload operation of refrigerant cycle
P22	Outdoor unit fan motor trouble • Inverter protection circuit was activated, or lock was detected at outdoor unit fan motor.	Inverter stops after alarm is detected. Pre-trip 10 times	Recovery at restart	1.Position detection trouble. 2.Outdoor unit fan motor overcurrent Protection circuit is activated. • Check outdoor unit control PCB. • See outdoor unit fan judgement methods.
P29	Lack of INV compressor wiring, INV compressor actuation failure, DCCT failure	Inverter stops after alarm is detected. Alarm is output when inverter stops (pre-trip) consecutively 10 times.	Recovery at restart	1.Stops immediately even when operations restarted. • Layer short on the compressor 2.Check HIC circuit. • Wiring trouble
H31	HIC trouble	Pre-trip consecutively 10 times	Temperature dropped	Heat sink and PCB (HIC) • Contact trouble

E04 Error in Indoor Unit Receiving Signal from the Outdoor unit

1. Error Detection Method

When there is no communication within a 3-minute period from the outdoor unit. Or, judged an error when no reply comes from the outdoor unit.

- The outdoor unit is not turned on.
- When the power was turned on after auto address setting was completed, the number of indoor units had been changed.
- · Forgot to turn on the indoor unit.
- The CHK pin and / or TEST pin on the indoor unit's control PC board are shorted.
- Forgot to install the nonvolatile memory (EEPROM) when replacing the indoor unit control PC board.
- Mistakenly set the indoor unit address to Not Set in the remote control's detailed setting mode.
- When indoor unit addresses are duplicated.
- There is a short, open, wrong contact or grounding of the indoor / outdoor control line*.
- There is an error in the receiving circuit on the signal output PC board (optional control PC board).
- · Malfunctions of the outdoor unit
- The thermistor inside the indoor unit is grounded.
- The capacity setting is mismatched between indoor units and the outdoor unit.

1 Power Source	1-1	Yes			After turning the power on, wait three minutes		
				1-2			
	4.0	Y		Yes	Power on		
	1-2 Is the indoor unit powered off?		No	2-1			
2 Indoor / outdoor			Yes	3-1			
wiring	- '	to the massiff satassi willing confidence confectly.	officeted correctly:		Correct the wiring		
3 Number	3-1	Was the number of indoor units increased or decreased after		Yes	3-2		
and setting of indoor	3-1	auto address setting was complete?		No	3-3		
units	3-2	Conduct checks prior to auto address setting.					
dinto		Check the indoor unit addresses from the remote control's		Yes	3-2		
	3-3	detailed settings mode. Is it Not Set (99), or is the indoor unit's address duplicated?	detailed settings mode.		3-4		
		cottings made		Yes	4-1		
	3-4			No	3-2		
4 Indoor	4-1	Are the CHK pin and / or TEST pin on the indoor unit control PC		Yes	Remove the short		
unit	board short-circuited?			No	4-2		
control PC board	4-2		Yes	4-3			
P C board			No	4-5			
	4-3	of the indoor drift control i C board, and see whether the Lot goes on		Yes	4-4		
	4-3 after several minutes. (When doing so, if two remote controllers are being used and the wireless remote controller is the main remote controller, set the other remote controller as the main.)		No	4-5			
	4-4	Replace wireless remote control parts including wiring.					
	4-5	Is the LED on the indoor unit control PC board blinking?	a the LED on the indeer unit central DC heard blinking?		4-6		
	4-5 Is the LED on the indoor unit control PC board blinking?	is the LLD on the indoor drift control i o board blinking:		No	4-7		
	4-6	The nonvolatile memory (EEPROM) on the indoor unit's control PC boar improperly installed or the nonvolatile memory is faulty. Correct this or a nonvolatile memory, write model data to it in the remote control detailed			replacing the		
	$_{1-7}$ Are all the remote controllers of the other indoor Yes $_{\rm ho}$		he o	outdoor unit both control C)			
		units connected to that outdoor unit displaying E04? No Replace the inc		door unit control board			


^{*} indoor / outdoor control line* : Connection cable between outdoor and indoor unit

- Regarding the remote controller check, refer to the Reference Materials.
- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit and / or replacing the indoor unit's control board, refer to the manual that is packaged with the indoor unit service board.

Outdoor Unit Control PCB (CR/HIC)

■ CR-PCB : ACXA73-33930 (U-100PZ3E5)■ CR-PCB : ACXA73-33950 (U-125PZ3E5,

U-140PZ3E5)



■ HIC-PCB : ACXA73-33940 (U-100PZ3E5)■ HIC-PCB : ACXA73-33960 (U-125PZ3E5, U-140PZ3E5)



■ CR-PCB : ACXA73-33970 (U-100PZ3E8, U-125PZ3E8, U-140PZ3E8)



■ HIC-PCB : ACXA73-33980 (U-100PZ3E8, U-125PZ3E8, U-140PZ3E8)






■ ACXA73-3440* : Middle Static Pressure Duct Type



■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E06 Outdoor Unit Failed to Receive Serial Communication Signals from Indoor Unit

(When indoor unit(s) are connected)

1. Error Detection Method

It is judged an error when there is no transmission (reply) from the indoor unit to the outdoor unit for a period of three minutes.

- The indoor unit is not turned on.
- The DISP pin of the indoor unit is shorted.
- There is a short, open, wrong contact or grounding of the indoor / outdoor control line*.
- The signal output control PC board (optional control PC board) inside the indoor unit has failed.
- The thermistor inside the indoor unit is grounded.

1 Indoor unit	1-1	Is the indoor unit powered off?	Yes	Power on
power		is the mador unit powered on:	No	2-1
2 Indoor / outdoor	2-1	Is the indoor / outdoor control line* shorted, opened,	Yes	Correct the wiring
wiring	_ '	grounded or has a wrong contact?	No	3-1
3 Indoor	3-1	Are the DISP pin and CHK pin on the indoor unit control PC board	Yes	Remove the short
units	3-1	short-circuited?	No	3-2
control PC board	3-2	is the wholes female controller confidence to on the mason drift's	Yes	3-3
. o source			No	3-5
	3-3	Disconnect the connector mentioned above on the control PC board of the indoor unit control PC board, and see whether the E06 goes off after several minutes. (When doing so, if two remote controllers are	Yes	3-4
	3-3	being used and the wireless remote controller is the main remote controller, set the other remote controller as the main.)	No	3-5
	3-4	Replace wireless remote control parts including wiring.		
	3-5	Indoor unit control PC board failure \rightarrow Replace board.		

[•] For information on the procedures for replacing the indoor unit's control board, refer to the manual that is packaged with the indoor unit control PCB.

^{*} indoor / outdoor control line* : Connection cable between outdoor and indoor unit


■ ACXA73-3129* : 4-Way Cassette Type



■ ACXA73-3440* : Middle Static Pressure Duct Type



■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E15 Auto Address Alarm (The total capacity of indoor units is too low.)

1. Error Detection Method

Connecting indoor unit

It is judged an error the total capacity of indoor units replied by communication is lower than that of outdoor unit.

- · The total capacity of indoor units is lower than that of outdoor unit
- Some indoor unit(s) are connected but power is not turned on
- The CHK pin (CN062 / CN071) and / or TEST pin (CN064) of the indoor unit is shorted when its power is turned on.

2. Error Diagnosis

1 Power	1-1	Is the indoor unit powered off?		Power on	
Source			No	2-1	
2 Indoor / outdoor			Yes	3-1	
wiring	2-1	Is the indoor / outdoor wiring connected correctly?	No	Correct the wiring	
3 Number of	of 3-1	er of 🔒 Was the number of indoor units changed after auto address setting	Yes	3-2	
Indoor		finished?	No	4-1	
Units	3-2	Conduct checks prior to auto address setting.			
4 Indoor		Do sure that the datailed action items are made at factory actions	Yes	4-2	
unit	4-1	Be sure that the detailed setting items are made at factory setting. [U3, F3, K3, T3]	No	Correct the setting Run the auto address	
PC board	4-2	, as are or at pin and 1201 pin or are indeed and contact scalar	Yes	Remove the short	
			No	4-3	
	4-3	io and wholese formets controlled controlled to on the massification	Yes	4-4	
			No	4-6	
		of the indoor unit control PC board and see whet	Disconnect the connector mentioned above on the control PC board of the indoor unit control PC board and see whether the E15 goes off after several minutes. (When doing so, if two remote controllers are	Yes	4-5
		being used and the wireless remote controller is the main remote controller, set the other remote controller as the main.)	No	4-6	
	4-5	Replace wireless remote control parts including wiring.			
	4-6	Is the LED blinking on the indoor unit's control PC board?	Yes	4-7	
	4-0		No	5-1	
	4-7	The nonvolatile memory (EEPROM) on the indoor unit's control board is either not insimproperly installed or the nonvolatile memory is faulty. Correct this or after replacing nonvolatile memory, write model data to it in the remote control detailed settings model.			
5 Outdoor unit control PC board	5-1 Check all items under the section "Check Prior to Auto Address Setting".				

· Factory setting

Item code	Item	Value
11	Indoor unit capacity	0
12	System address	99
13	Indoor unit address	99
14	Group control address	99

NOTE

The Item code numbers 11, 12, 13 and 14 can automatically be changed to the appropriate settings from factory settings listed above by making the auto address settings according to the connected outdoor unit capacity and the number of indoor units.

If needed to reset the settings after once changed, return all the item codes to the factory shipment-time settings. It is necessary to set the auto address settings once again.

- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit, refer to the manual that is packaged with the indoor unit service board.
- For information on the remote control's detailed settings, see 7-3 and 7-4.
- The alarm also occurs when the indoor unit cannot be recognized (indoor unit only blackout, disconnection of indoor / outdoor control line*, etc.) during auto address setting.

■ ACXA73-3129*: 4-Way Cassette Type




■ ACXA73-3440* : Middle Static Pressure Duct Type



^{*} indoor / outdoor control line* : Connection cable between outdoor and indoor unit

■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E16 Auto Address Alarm (The total capacity of indoor units is too high.)

1. Error Detection Method

It is judged an error the total capacity of indoor units is too high or the total number of indoor units is too many.

- The total capacity of indoor units is too high.
- The total number of indoor units is too many.
- When making group control of the different refrigerant system, the steps to turn on the systems one at a time have not been performed.

1 Auto Address	1-1	Conduct checks prior to auto address setting.	
-------------------	-----	---	--

E20 Auto Address Alarm (No indoor unit connected)

1. Error Detection Method

The outdoor unit detects an error at following cases during auto address setting.

- Indoor unit is not turned on.
- Indoor / outdoor control line* is disconnected and also detects an error in the following cases when the outdoor unit is turned on.
- Address(es) of indoor unit(s) are not assigned correctly.
- Capacity of indoor / outdoor units is mismatched.
- Total number of indoor units is too many.

1 Indoor Unit	1-1	Are the address(es) of indoor unit(s) assigned correctly?		Yes	1-2
	1-1 Are the address(es) of indoor drift(s) assigned correctly?			No	Set its address
	1-2	Are the indoor units turned on?		Yes	1-3
				No	Power on
1-3 Be sure that the indoor an		Be sure that the indoor and outdoor units are connected with	Yes	1-4	
	1-3		Correct the connection		
	1-4	The indoor / outdoor control line* may be disconnected somewhe and the outdoor unit. Make sure the indoor / outdoor control line*	re be is co	e between the indoor unit(s s connected.	

^{*} indoor / outdoor control line* : Connection cable between outdoor and indoor unit

F04 Compressor Discharge Temperature Sensor (TD) Trouble

1. Error Detection Method

It is judged an error based on the criteria listed below.

• Open circuit or Short circuit

1 Sensor	1-1	Sensor connector is connected to PC board properly.	Yes	1-2
			No	Reconnect and check
		Sensor is correctly installed at holder side.	Yes	Replace sensor
	1-2		No	Correct and see what happens.
		Abnormal temperature exists even after replacing sensor.	Yes	1-3 2-1
	1-3		-	See what happens.
2 PC board	2-1	Resistance between connector pins on PC board is less than 1 k ohm	Yes	Replace PC board
			No	2-2
	2-2	Abnormal temperature exists even after replacing PC board.	Yes	3-1
			No	See what happens.
3 Operating	3-1	Peripheral temperature of outdoor unit is over 43°C.	Yes	Correct
status			No	3-2
	3-2	Tends to have insufficient refrigerant charge in the system.	Yes	Adjust the amount of refrigerant
			No	3-3
	3-3	Check noise.	·	

F06 Inlet Temperature Sensor (C1) in Heat Exchanger Trouble

1. Error Detection Method

• In case of open or short

1 Sensor Trouble	1-1	Is the connector properly connected to PCB?	Yes	1-2
			No	Reconnect & check
	1-2	Is the resistor between the sockets infinity or 0Ω ?	Yes	Replace sensor.
		is the resistor between the sockets infinity of 012?	No	2-1
2 Control PCB Failure	2-1	Outdoor unit control PCB failure Replace PCB with a new one.		

F07 Intermediate Temperature (C2) in Heat Exchanger Trouble

1. Error Detection Method

It is judged an error when open circuit or short circuit.

1 Sensor	1-1	Sensor connector is connected to PC board properly.	Yes	1-2
	1-1	Sensor connector is connected to PC board properly.	No	Reconnect and check
	1-2	Resistance between sockets is infinity or 0 ohm.	Yes	Replace sensor
			No	2-1
2 PC board	2-1	Replace PC board because of outdoor control PC board failure.		

F08 Outdoor Air Temperature Sensor (TO) Trouble

1. Error Detection Method

It is judged an error when open circuit or short circuit.

1 Sensor 1-	1 1	Sensor connector is connected to PC board properly.	Yes	1-2
	1-1	Sensor connector is connected to PC board properly.	No	Reconnect and check
	1-2	Resistance between sockets is infinity or 0 ohm.	Yes	Replace sensor
			No	2-1
2 PC board	2-1	Replace PC board because of outdoor control PC board failure.		

F12 Compressor Inlet Suction Temperature Sensor (TS) Trouble

1. Error Detection Method

It is judged an error when open circuit or short circuit.

1 Sensor	1 1	-1 Sensor connector is connected to PC board properly.	Yes	1-2
	1-1		No	Reconnect and check
	1-2	Resistance between sockets is infinity or 0 ohm.	Yes	Replace sensor
			No	2-1
2 Outdoor control PC board	2-1	Replace PC board because of outdoor control PC board failure.		

F31 Outdoor Unit Nonvolatile Memory (EEPROM) Trouble

1. Error Detection Method

It is judged an error based on the criteria listed below.

- When power initially turned ON for the first time, nonvolatile memory (EEPROM) is not installed.
- Read values after writing onto nonvolatile memory (EEPROM) is inconsistent.

1 PC board	1-1	Does EEPROM exist on the control PC board?	Yes	1-2
			No	Install EEPROM
	1-2	Is EEPROM installed properly?	Yes	1-3
		(Check: Bent IC pin or incorrect installation, etc.)	No	Correct
	1-3	Incorrect EEPROM Replace with correct EEPROM.		

H01 Primary (input) Overcurrent Detected

1. Error Detection Method

• Primary current effective value detected overcurrent (trip current value).

Туре				P	Z3		
Model name (U-)		100PZ3E5	125PZ3E5	140PZ3E5	100PZ3E8	125PZ3E8	140PZ3E8
Trip current value	Heating	27.6A	33.0A	33.5A	13.5A	14.5A	15.0A
	Cooling	27.6A	32.0A	32.5A	13.2A	14.2A	14.5A


4.5	Т		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
1 Power	1_1	Not satisfied with ±10% rated supply voltage	Yes	Check power supply
supply*		Two satisfied with ±10% rated supply voltage	No	1-2
		Extreme voltage fluctuations	Yes	Check power supply
	1-2	Extreme voltage fluctuations	No	1-3
		Extreme distortion of voltage waveform	Yes	Check power supply
		Extreme distortion of voltage waveform	No	1-4
		Instantaneous blackout may comotimes occur	Yes	Check power supply
		Instantaneous blackout may sometimes occur.	No	2-1
2 PC board	2-1	Has FUSE 1-A / FUSE 2 and FUSE 3 blown?	Yes	2-3
wiring		Check the electrical conduction with tester.	No	2-2
	2-2	Loose electrical wire connection	Yes	Correct wiring
	2-2	Loose electrical wife confidential	No	2-3
	2-3	Replace CR board.		

^{*} Check not only in the outdoor unit stop mode but in the drive mode.

For Single-Phase Outdoor Unit PCB


■ CR-PCB : ACXA73-33930 (U-100PZ3E5)

■ CR-PCB: ACXA73-33950 (U-125PZ3E5, U-140PZ3E5)



For 3-Phase Outdoor Unit PCB

■ CR-PCB: ACXA73-33970 (U-100PZ3E8, U-125PZ3E8, U-140PZ3E8)



H02 PAM Trouble (Single-phase only)

1. Error Detection Method

• Error is detected by over-voltage and overcurrent of DC side.

1 Power	1-1	Not actisfied with ±100/ rated aupply voltage	Yes	Check power supply
supply*	1-1	Not satisfied with ±10% rated supply voltage	No	1-2
	1.2	Extreme voltage fluctuations	Yes	Check power supply
	1-2	Extreme voltage fluctuations	No	1-3
	1-3	Extreme distortion of voltage waveform		Check power supply
	1-3	Extreme distortion of voltage waveform	No	2-1
2 PC board wiring	2-1	Lagge electrical wire connection	Yes	Correct connection
		Loose electrical wire connection	No	2-2
	2-2	Replace HIC PC board.		

^{*} Check not only in the outdoor unit stop mode but in the drive mode.

H03 Primary Current CT Sensor (current sensor) Failure

1. Error Detection Method

It is judged an error based on the criteria listed below.

- If 18A or greater is detected when the compressor is stopped (alarm triggered even if the connector is unplugged).
- If no current is detected even though a compressor is running.

2. Error Diagnosis

1 Check the	1_1	Turn the power on again and run the outdoor unit.	Yes	Replace CR board.
control 1 PC board	1-1		No	See what happens.

• Check also the power supply.

H31 HIC Trouble

1. Error Detection Method

It is judged an error if the computer detects an error signal from the HIC.

An error signal is issued by the HIC if abnormal heat occurs inside the HIC or if there is an overcurrent.

However, it is judged an error in the same way if the signal line from the HIC is not connected properly or opened.

- · HIC overcurrent due to HIC fault
- · HIC abnormal heat caused by defective HIC or HIC radiation error
- Signal line is not connected properly or opened between the HIC and the outdoor CR board.

2. Error Diagnosis

1 Wiring	4.4	The wiring (power cord and signal line) between the HIC	Yes	1-2
between HIC &	1-1	and the outdoor CR board is connected properly.	No	Correct wiring (connector)
outdoor control PC board	1-2	Everything is normal in the wiring (power cord & signal line) between the HIC and the outdoor CR board. Check the wiring one by one with a tester if there is opened and	Yes	2-1
1 C board				Replace wiring
2 HIC poor radiation	2-1	The heat dissipating surface on the back of the HIC is in good contact with the heat sink (heat dissipating fins) of the electrical box. Check for looseness in the fastening screws and the condition of the heat-conducting putty.		2-2
	2-1			Tighten screw(s), add putty
	2-2	A good flow of cooling air passes through the heat sink (heat dissipating fins) of the electrical box. Check for debris blocking the fins. The results of the pass / fail tests for the following HIC board IPM show it to be outside the range of the resistance of a conforming part.		3-1
	2-2			Remove foreign matter
3 HIC overcurrent	3-1			Replace the HIC PC board
ovorounom.	3-1			3-2
	3-2	The inverter compressor was stopped / started more than 10 times and it triggered H31 at a high rate. If alarm code P16	Yes	Replace the HIC PC board
	5-2	times and it triggered H31 at a high rate. If alarm code P16 occurs at times, refer to the alarm code P16.		Refer to alarm code P16

• HIC board IPM Pass / Fail Tests

- Measure with an analog tester. (Set to the k ohm range)
- Measure the board by itself. (Remove wires connected from other parts.)
- Measure using IPM terminals.

★ Conforming part resistance value (measure with an analog tester)

Tester terminals								
+		F)			I	NU	
-	U	V	W	NU	U	V	W	Р
Resistance value (ohm)	value (ohm)		5 k to 10 k	100 k to ∞				
Tester terminals								
-		F)			ı	NU	
+	U	V	W		U	V	W	
Resistance value (ohm)	100 k to ∞	100 k to ∞	100 k to ∞		1 k to 5 k	1 k to 5 k	1 k to 5 k	

 Excepting the parts of "100 k to ∞", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".

Tester terminals								
+		HIG	C+			F	IIC-	
-	U	V	W	HIC-	U	V	W	HIC+
Resistance value (ohm)	1 k to 10 k	1 k to 10 k	1 k to 10 k	5 k to 20 k	20 k to ∞			
Tester terminals								
Tester terminals		HIG	C+			F	IIC-	
	U	HIG	C+		U	V	HIC-	

[•] Excepting the parts of "20 k to ∞ ", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".

For Single-Phase Outdoor Unit HIC PCB

■ HIC-PCB : ACXA73-33940 (U-100PZ3E5)

■ HIC-PCB : ACXA73-33960 (U-125PZ3E5, U-140PZ3E5)



For 3-Phase Outdoor Unit HIC PCB

■ HIC-PCB : ACXA73-33980 (U-100PZ3E8, U-125PZ3E8, U-140PZ3E8)



L10 Outdoor Unit Capacity not Set or Invalid

1. Error Detection Method

It is judged an error when outdoor unit capacity not yet setup or systematically unauthorized setting.

PC board		1 Check the control PC board	1-1	Was EEPROM replaced when PC board was replaced?
----------	--	------------------------------	-----	---

L13 Indoor Unit Type Setting Error

1. Error Detection method

• Discordance model(s) between outdoor and indoor units are detected.

1 Discordance Unit	1-1	Are models for outdoor and indoor units matched respectively? (Ex: Are multiple indoor units connected to commercial outdoor units?)	Yes No	2-1 Replace indoor units.
2 Installation Failure 2-1		Check the indoor unit's motor valve with the remote control detailed settings mode (2C code) and commercial indoor unit is set to "2" and	Yes	3-1
ranaro	_ '	multiple indoor unit is "0".	No	Change installation.
3 Operating Wires for Indoor & Outdoor Units	3-1	Check whether or not indoor and outdoor unit operating wires are shot loose connection or earth fault.	t circ	cuit, disconnection,

L18 4-Way Valve Operation Failure

1. Error Detection method

It is judged an error when during heating operation (Comp. ON), the highest detected temperature at an outdoor unit heat exchanger (C1) was 20°C or more above the outdoor air temperature (Air Temp.) continuously for 5 minutes or longer.

1 PC board	1-1	Is the connector wired from the 4-Way valve plugged in the CN-HOT or CN-HOT2 connector on the CR PC board properly?		1-2
wiring	1-1			Correct connector
	1-2	Llee the 4 Mey value witing become enough		Correct wiring
	1-2	Has the 4-Way valve wiring become opened?	No	1-3
	4.0	Is the wire from the coil for controlling the 4-Way valve firmly	Yes	2-1
2 4-Way valve	1-3	connected to the 4-Way valve?		Correct connector
	2-1	During heating mode (Comp. ON), insert and remove the connector wired from the 4-Way valve into or from CN-HOT or CN-HOT2		2-2
	2-1	connector on the CR PC board. At the same time, does the ON & OFF sounds occur from the 4-Way valve?	No	Replace CR PC board
	2-2	During heating mode (Comp. ON), does the alarm code L18 reproduce for 5 minutes or longer after insertion and removal of	Yes	2-3
		CN-HOT or CN-HOT2 connector wired from the 4-Way valve connector on the CR PC board?	No	See what happens
	2-3	The parts inside the 4-Way valve might have fixed at the cooling side. Replace the 4-Way valve		

P03 Compressor Discharge Temperature Trouble

1. Error Detection method

• When the discharge temperature is over 103°C.

1 Adjustment to	1-1	Not additional refrigerant charged		Additional refrigerant charge
refrigerant charge			No	2-2
	1-2	Tends to have insufficient refrigerant charge in the system.	Yes	Adjust the refrigerant amount
				Replace CR board
2 Blockage in	2-1	Service valve inside the outdoor unit closed		Open service valve
refrigerant circuit		Service valve iriside the odtdoor drift closed	No	2-2
	2-2	Are the tubes clogged?		Avoid clogging
	2-2			2-3
		le the outdoor unit's electronic control valve enerating correctly?		2-4
	2-3	Is the outdoor unit's electronic control valve operating correctly? (Check for debris clogging the electronic control valve, a problem with the electronical coil and / or the control PC board.)	No	Replace the electronic control valve
	2-4	Is it observable difference in status of the dew or frost between	Yes	Replace the strainer
	Z-4	the strainer's primary and secondary sides?	No	Replace CR board

P04 High Pressure Trouble

1. Error Detection Method

It is judged an error if the internal circuit of the high pressure switch is dead.

The electronic circuitry of the high pressure switch is cut off if the pressure at the pressure sensor port of the high pressure switch reaches 4.15 MPa. Once it is cut off, it remains cut off until the pressure drops to 3.05 MPa.

- The high pressure switch is malfunctioning.
- · Service valve inside the outdoor unit closed
- There is a short air circuit through the outdoor unit's heat exchanger. (when cooling)
- The outdoor unit's fan is broken. (when cooling)
- The outdoor unit's heat exchanger is clogged. (when cooling)
- There is a short air circuit at the indoor unit. (when heating)
- The filter of the indoor unit is clogged. (when heating)
- The fan of the indoor unit is broken or the fan motor is malfunctioning. (when heating)
- The refrigerant circuit is closed and the high pressure is increasing abnormally high. (solenoid valve or expansion valve not activated, a stuck check valve, etc.)
- · Refrigerant overcharged.
- Nitrogen or air contaminated in the refrigerant system

1 High		The cocket of the high pressure quitable accuraty incerted in the	Yes	1-2
pressure switch	1-1	The socket of the high pressure switch is securely inserted in the PC board. The wiring is not opened.	No	Correct connection and / or wiring
	1-2	Even if parts near the high pressure switch are shaken quite a lot, the high pressure cut off will be activated. Even if the covering is in good condition, in several cases vibration	Yes	Replace the high pressure switch (wiring)
		has caused wiring inside to open.	No	2-1
2 Service valve	2-1	Service valve inside the outdoor unit closed	Yes	Open the service valve
				2-2
	2-2	There is an extreme difference in temperature in / out of the service		2-3
			No	3-1
	2-3	Check the flare connection, someone may have forgotten to remove If there is a problem within the service valve, replace the valve.	the b	oonnet.
3 Problem	2.4	M/hile cooling is expecting on clarge is executed	Yes	3-2
around the	3-1	While cooling is operating an alarm is occurred.	No	3-5
heat exchanger	3-2	The intake temperature (ambient temperature) of the outdoor unit's		Prevent air short circuit
		heat exchanger is above 43°C.		3-3
	3-3	The outdoor unit's heat exchanger is clogged.		Clean the heat exchanger
				3-4
		Chack whather the outdoor unit fan is normal ar if the cookets are	Yes	4-1
	3-4 Check whether the outdoor unit fan is normal or if the sockets are firmly pressed onto the plugs on the outdoor PC board, as well a if any wiring is opened. Are these checking finished without fail?	firmly pressed onto the plugs on the outdoor PC board, as well as if any wiring is opened.	No	Replace the outdoor unit fan. Correct connection and / or wiring
	3-5	While heating is operating an alarm is occurred	Yes	3-6
	3-3	While heating is operating an alarm is occurred.	No	4-1
1				

I	L			
3 Problem around the	3-6	The intake temperature (ambient temperature) of the indoor unit is above 36°C.	Yes	Prevent air short circuit
heat exchanger		above ee e.	No	3-7
exchanger	3-7	The filter of the indoor unit is clogged.	Yes	Clean the filter
	3-7	The litter of the indoor drift is clogged.	No	3-8
	3-8	The fan of the indoor unit is broken or the fan motor is faulty.	Yes	Replace the indoor fan (motor)
			No	4-1
4 Blockage		Is the outdoor unit's electronic control valve operating correctly?	Yes	4-3
in the refrigerant circuit	4-1	(Check for debris clogging the electronic control valve, a problem with the electronical coil and / or the control PC board.)	No	Repair the electronic control valve of the outdoor unit
		The indeer unit's expansion valve is energing correctly	Yes	4-3
	4-2	The indoor unit's expansion valve is operating correctly. (check for debris clogging the valve, a problem with the electronical coil and / or the control PC board)	No	Repair the expansion valve of the indoor unit
		If an alarm is accurred with the high proceure below 4.15 MPa	Yes	4-4
	4-3 with the pressure measured as displayed by the manifold gauge, check the check valve in the compressor discharge line. Are these checking finished without fail?		No	Replace the check valve in the compressor discharge line
			Yes	Replace the electronic control valve and / or solenoid valve.
			No	5-1
5	5-1	Error occurs when the system is operating in cooling mode.	Yes	5-3
Overcharging	5-1	Error occurs when the system is operating in cooling mode.	No	5-2
	- 0		Yes	5-4
	5-2	Error occurs when the system is operating in heating mode.	No	5-5
	5-3	An alarm is occurred with the high pressure at 4.15 MPa, with the pressure measured either as displayed by the monitoring software or with a manifold gauge, at which time the temperature of liquid in	Yes	5-5
		the outdoor unit's heat exchanger is detected to be at the temperature of the outside air.	No	Contact the service representative
		An alarm is occurred with the high pressure at 4.15 MPa, with the pressure measured either as displayed by the monitoring software		5-5
	5-4	or with a manifold gauge, at which time the temperature of liquid in the indoor heat exchanger is detected to be at room temperature (intake temperature).	No	Contact the service representative
	5-5	The system may be overcharged. Check how much refrigerant was a When a system is inspected for airtightness, it is seldom that enough expelled, so some remains in the circuit. In this case, it is necessary to collect the refrigerant and then recharge	nitro	ogen has been

P05 AC Power Supply Trouble

1. Error Detection Method

- · Instantaneous blackout
- · Zero-cross (waveform input of power supply) error
- DC voltage charge failure

2. Error Diagnosis


Note: The work involved in diagnosing each of the items is extremely dangerous, so turn the power off at the breaker before performing the tests.

1 Check the power	Is the voltage on each of the 1-1 terminal boards within ±10%		Yes	1-2 : 3-pnase model				
supply & the wiring		of the rated voltage?	Observation and a servation of the serva		d the voltage at the breaker. t and check again.			
	1-2	Power wiring L1 and L3 are conne	otoc	ı	Yes	Correct wiring		
	1-2	Power willing L1 and L3 are confid	ectec	l.	No	1-3		
	1-3	Turn the power back on and chec	k aga	ain.	Yes	2-1		
	1-3	Is the alarm triggered again?			No	3-1		
2 Check the	2-1	Are the wires (RE1, RE2) from the	e rea	ctor firmly installed?	Yes	2-2		
outdoor	2-1	Are the wires also connected to the	ne sid	de of the reactor?	No	Correct wiring		
unit HIC PC board	2-2	Turn the power back on and check again.		Yes	Replace the outdoor unit HIC PC board.			
		Is the alarm triggered again?			No	3-1		
3 Final check	3-1	_	There may be a instantaneous blackout failure. If there is nothing abnormal, see what happens.					

For Single-Phase Outdoor Unit HIC PCB


■ HIC-PCB: ACXA73-33940 (U-100PZ3E5)

■ HIC-PCB: ACXA73-33960 (U-125PZ3E5, U-140PZ3E5)



For 3-Phase Outdoor Unit HIC PCB

■ HIC-PCB : ACXA73-33980 (U-100PZ3E8, U-125PZ3E8, U-140PZ3E8)



P13 Alarm Valve Open

1. Error Detection Method

Detection is performed only in the test run. When once detected or the test run finished without any error, the second detection will not be done.

In case of forgetting to open a valve, P04 (high-pressure switch operational alarm) is occasionally preceded due to the following conditions.

• The status of small temperature change of the operating indoor unit continues for the first 7 minutes since the cooling test run has started.

1 Service valve	1-1	1-1 Service valve inside the outdoor unit closed		Open the service valve
				2-1
2 Adjustment to	2-1	Not additional refrigerant charged	Yes	Additional refrigerant charge
refrigerant change		Tiot additional romigorant onal god	No	3-1
3 Blockage	3-1	Are the tubes closed?		Avoid clogging
in	3-1	Are the tubes clogged?	No	3-2
refrigerant circuit		le the outdoor unit's electronic control valve energing correctly?	Yes	3-3
	3-2	Is the outdoor unit's electronic control valve operating correctly? (Check for debris clogging the electronic control valve, a problem with the electronical coil and / or the control PC board.)	No	Replace the electronic control valve
	3-3	As the second detection is not done, restart and see what happens i	f ther	e is no error.

P15 Insufficient Gas Level Detected

1. Abnormal Detection Method

Alarm occurs in the following cases:

- Compressor's current value shows lower than a certain value.
- Compressor's discharge temperature exceeds 95°C.
- Electronic expansion valve is fully opened.
- The difference between indoor unit heat exchanger temperature and intake temperature is less than 4K.

1 Adjustment of	1-1	Insufficient gas level (Check whether or not pressure level is normal.)	Yes	Recharge with additional refrigerant.
refrigerant amount		(Check whether of hot pressure level is hormall)	No	1-2
amount	1-2	Check leakage of refrigeration (leak test)	Yes	Replace leaking part with a new one.
				See what happens.

P16 Compressor Overcurrent Trouble

1. Meaning of Alarm

• Secondary current effective value detected the overcurrent (trip current value).

Туре				PZ	Z3		
Model name	e (U-)	100PZ3E5	125PZ3E5	140PZ3E5	100PZ3E8	125PZ3E8	140PZ3E8
Trip current value	Cooling	17.5A	19.5A	19.5A	11.5A	13.0A	13.0A
	Heating	17.5A	19.5A	19.5A	11.5A	13.0A	13.0A

2. Check of content

0 Multiple	0-1	Replaced the compressor (added oil, if it was necessary)	Yes No	7-1
factors		but it occurred again immediately.		-
	0-2	Replaced the board, but it occurred again immediately.	Yes	Replace compressor along with adding oil, then recheck from 1-1
			No	-
1 Power	1-1	Power cord connections are loose.	Yes	Correct the wiring
Source		Tower cord connections are locate.	No	1-2
	1-2	Rated power voltage is not within ±10%.		Test the power supply
		Trated power voltage is not within ±10%.	No	1-3
	1-3	Extreme fluctuations in voltage.		Test the power supply
				1-4
	1-4	An open phase state is observed.		Test the power supply
0 D I			No	2-1
2 Board wiring	2-1	are observed in the connections on the CR board and / or in the		Correct
		connections of components that are connected by wiring from the CR board.	No	2-2
	2-2	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of outdoor board(s) that are	Yes	Correct
		connected by wiring from the CR board.	No	2-3
	2-3	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of outdoor board(s) that are	Yes	Correct
		connected by wiring from the HIC board.	No	2-4
	2-4	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of HIC boards connected by	Yes	Correct
		wiring from the CR board.	No	2-5
	2-5	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of HIC board(s) that are	Yes	Correct
	2-3	connected by wiring from the outdoor board.	No	2-6
	2-6	Disconnected parts, miswiring and / or poor connections (loose)	Yes	Correct
2-6		are observed in the connections of HIC board(s) that are connected by wiring to a compressor.		3-1

	1			T
3	3-1	Disconnections and / or miswiring are observed in the		Correct
Compressor wiring	J 1	connecting location of the compressor terminals.	No	3-2
wiiiig	Conditions such as burned terminal covers and / or disc 3-2 terminals are observed in the connecting location of the compressor terminals.		Yes	Eliminate looseness by changing the terminals, or crimping the terminals again.
			No	4-1
4 Check the	4-1	Outdoor air intake temperature is high.	Yes	Take measures
situation	4-1	Outdoor all intake temperature is high.	No	4-2
	4-2	May be caused by poor outdoor unit air flow	Yes	Correct
	4-2	(dirty or clogged heat exchanger, blocked discharge port, etc.)	No	4-3
	4-3	Air short circuit has occurred. This is a phenomenon when discharged air (exhaust heat) from the outdoor unit is drawn back	Yes	Prevent air short circuit
		into the suction vent.		4-4
	4-4	Indoor air intake temperature is high.		Take measures
				4-5
	4-5	The filter of the indoor unit is clogged.		Clean the filter
		A: 1	No	4-6
	4-6	Air short circuit has occurred. This is a phenomenon when discharged air (exhaust heat) from the indoor unit is drawn back	Yes	Prevent air short circuit
		into the suction vent.	No	
5 Check operation	5-1	Possible to operate.	Yes	
Operation		'	No	
	5-2	Operating pressure is affected by pressure overload.	Yes	
		7.	No	5-4
	5-3	Tends to have an overcharge of refrigerant in the system.	Yes	Adjust the amount of refrigerant
			No	5-4
	5-4	Tends to operate for a long time turning gas back into liquid.	Yes	Check the operation of functional parts
			No	5-5
	5-5	Tends to have insufficient refrigerant charge in the system.	Yes	Adjust the amount of refrigerant
			No	5-6
	5-6	Even though the high pressure saturation temperature is 43°C or less, the secondary current of the inverter is high.	Yes	Replace the compressor
		(The frequency (Hz) ends up dropping due to the current.)	No	See what happens.
6 Check	6-1	Dividing the outdoor EEPROM INV operation time by the number	Yes	6-2
history	<u> </u>	of times oil was supplied to the system yields 3 hours or less.	No	6-2
	6-2	There is a history of H31 in the pre-trip counter of the outdoor EEPROM alarm history.	Yes	Replace the compressor and add oil. However, if 6-1 was "no", it is not necessary to add oil.
			No	7-1
7 Check the HIC boards	7-1	The results of HIC board IPM Pass / Fail Tests show the outside the range of the resistance of a conforming part listed in the next	Yes	Replace HIC board
		page.	No	8-1

8 Check the compressor	8-1	The compressor is causing a failure in the insulation.		Replace the compressor
				8-2
	8-2	The winding resistance of the compressor is abnormal. See "5-3. (3) Coil Resistance of Compressor ".		Replace the compressor
		coo o o. (a) con readictarios of compressor :	No	9-1
9 Check the HIC PC	9-1	Replace the HIC PC board and operate the unit. (Apply putty and		See what happens.
boards		screws must not be loose) Does it operate normally?	No	10-1
10 Check the outdoor unit main PC board	10-1	Replace the control PC board and operate the unit.	See	what happens.

- (Check content of 7) The test check of the HIC board is only a check on the output level, so the input stage may
 not be working.
- With the filter board broken, alarm P16 may not be triggered.
- HIC board IPM Pass / Fail Tests
 - Measure with an analog tester. (Set to the k ohm range.)
 - Measure the board by itself. (Remove wires connected from other parts.)
 - · Measure using IPM terminals.

★ Conforming part resistance value (measure with an analog tester)

Tester terminals								
+	Р				NU			
-	U	V	W	NU	U	V	W	Р
Resistance value (ohm)	1 k to 5 k	1 k to 5 k	1 k to 5 k	5 k to 10 k	100 k to ∞			
Tester terminals								
Tester terminals		F)			ı	NU	
Tester terminals - +	U	F V	W		U	V	NU W	

• Excepting the parts of "100 k to ∞", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".

Tester terminals								
+	HIC+			HIC-				
-	U	V	W	HIC-	U	V	W	HIC+
Resistance value (ohm)	1 k to 10 k	1 k to 10 k	1 k to 10 k	5 k to 20 k	20 k to ∞ 20 k to ∞		20 k to ∞	20 k to ∞
Tester terminals			<u> </u>	<u> </u>			<u>'</u>	
Tester terminals		HIG	C+			F	IIC-	
	U	HIG	C+		U	V	HC-	

• Excepting the parts of "20 k to ∞", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".

For Single-Phase Outdoor Unit HIC PCB

■ HIC-PCB : ACXA73-33940 (U-100PZ3E5)

■ HIC-PCB : ACXA73-33960 (U-125PZ3E5, U-140PZ3E5)



For 3-Phase Outdoor Unit HIC PCB

■ HIC-PCB : ACXA73-33980 (U-100PZ3E8, U-125PZ3E8, U-140PZ3E8)



P22 Outdoor Unit Fan Motor Trouble

1. Error Detection Method

• It is judged an error when the outdoor fan motor's rotating signal cannot be detected normally.

1 Wiring		Is the connector "CN-FM" firmly connected to the outdoor		2-1		
	Is the connector "CN-FM" firmly connected to the outdoor control PC board (lock engaged)?		No	Correct the connector connections		
2 Outdoor		Disconnect the connector "CN-FM" from the outdoor control PC	Yes	3-1		
fan motor	2-1	board and rotate the outdoor fan by hand; does it rotate freely? (Check the outdoor fan motor lock)	No	Replace the outdoor fan motor		
3 Outdoor control	3-1	Turn the power on and run the unit again; is P22 triggered again? Or can you see or hear anything that is obviously		3-2		
PC board	3-1	wrong in its rotation?	No	3-3		
	3-2	Replace the outdoor control PC board. (If it fails to operate normally even after replacing the outdoor control PC board, replace the outdoor fan motor.)				
	3-3	If there is nothing particularly out of the ordinary, see what happe	ns.			

P29 Lack of INV compressor wiring, INV compressor actuation failure (including locked), DCCT failure

1. Error Detection Method

- Abnormal current is detected at DCCT before start-up.
- Start-up failed during overcurrent and / or step-out detected.
- Open-wire of compressor and / or backspin detected.
- Secondary current is not detected during INV compressor is running.

2. Error Diagnosis

1 Wiring	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of HIC PC board(s) that are connected by wiring to a compressor. *1		Yes	Correct wiring connections
			No	1-2
	1-2	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of outdoor board(s) that are	Yes	Correct wiring connections
		connected by wiring from the HIC PC board. *1	No	2-1
2	2-1	Disconnections and / or miswiring is observed in the connections	Yes	Correct
Compressor	2-1	of the compressor terminals. *1	No	2-2
wiring	2-2	Conditions such as burned terminal covers and / or discolored terminals are observed at the connectors of the compressor terminals. *1	Yes	Eliminate looseness by changing the terminals, or crimping the terminals again.
			No	3-1
3 Check the HIC PC	3-1	The results of the pass / fail tests for the following HIC PC board IPM show it to be outside the range of the resistance of a	Yes	Replace the HIC board
boards		conforming part.	No	3-2
	3-2	Replace the HIC PC board and operate the unit. (Apply putty	Yes	See what happens.
	3-2	and screws must not be loose) Does it operate normally?	No	4-1
4 Check the outdoor control PC board	4-1	Replace the control PC board and operate the unit.	See	what happens.

^{*1} Checking for looseness of compressor terminals by wiggling them has the adverse effect of loosening them, so do not do it.

Evaluate them by discoloration of wire insulation near the terminal.

• HIC board IPM Pass / Fail Tests

- Measure with an analog tester. (Set to the k ohm range.)
- Measure the board by itself. (Remove wires connected from other parts.)
- Measure using IPM terminals.

★ Conforming part resistance value (measure with an analog tester)

Tester terminals								
+		F)		NU			
-	U	V	W	NU	U	V	W	Р
Resistance value (ohm)	1 k to 5 k	1 k to 5 k	1 k to 5 k	5 k to 10 k	100 k to ∞			
Tester terminals								
-		Р			NU			
+	U	V	W		U	V	W	
Resistance value (ohm)	4001-4-	100 1: 45	100 k to ∞		1 k to 5 k	1 k to 5 k	1 k to 5 k	

 Excepting the parts of "100 k to ∞", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".

Tester terminals								
+	HIC+			HIC-				
-	U	V	W	HIC-	U	V	W	HIC+
Resistance value (ohm)	1 k to 10 k	1 k to 10 k	1 k to 10 k	5 k to 20 k	20 k to ∞	20 k to ∞	20 k to ∞	20 k to ∞
Tester terminals								
-		HIG	C+			F	IIC-	
+	U	V	W		U	V	W	
Resistance value (ohm)	20 k to ∞	20 k to ∞	20 k to ∞		1 k to 10 k	1 k to 10 k	1 k to 10 k	

 Excepting the parts of "20 k to ∞", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".

P31 Group Control Error

1. Error Detection Method

• Other indoor unit alarms within the group.

1 Other indoor	1 1	Survey the indoor unit that alarms other than "P31" in the indoor unit group and specify the
unit	1-1	causes of failure.

For Single-Phase Outdoor Unit HIC PCB

■ HIC-PCB : ACXA73-33940 (U-100PZ3E5)

■ HIC-PCB : ACXA73-33960 (U-125PZ3E5, U-140PZ3E5)



For 3-Phase Outdoor Unit HIC PCB

■ HIC-PCB : ACXA73-33980 (U-100PZ3E8, U-125PZ3E8, U-140PZ3E8)



5-2-2-3. U-71PZH3E5, U-100PZH3E5, U-125PZH3E5, U-140PZH3E5 U-71PZH3E8, U-100PZH3E8, U-125PZH3E8, U-140PZH3E8

Alarms for outdoor units

Alarm Code	Alarm Meaning
E04	Error in Indoor Unit Receiving Signal from the Outdoor Unit
E06	Outdoor Unit Failed to Receive Serial Communication Signals from Indoor Unit
E15	Auto Address Alarm (The total capacity of indoor units is too low.)
E16	Auto Address Alarm (The total capacity of indoor units is too high or the total number of indoor units is too many.)
E20	Connection Problem of Indoor / Outdoor Units.

F04	Compressor Discharge Temperature Sensor (TD) Trouble
F06	Inlet Temperature Sensor (C1) in Heat Exchanger Trouble
F07	Intermediate Temperature Sensor (C2) in Heat Exchanger Trouble
F08	Outdoor Air Temperature Sensor (TO) Trouble
F12	Compressor Inlet Suction Temperature Sensor (TS) Trouble
F31	Outdoor Unit Nonvolatile Memory (EEPROM) Trouble

H01	Primary (input) Overcurrent Detected
H02	PAM Trouble
H03	Primary Current CT Sensor (current sensor) Failure
H31	HIC Trouble

L10	Outdoor Unit Capacity not Set or Invalid
L13	Indoor Unit Type Setting Error
L18	4-Way Valve Operation Failure

P03	Compressor Discharge Temperature Trouble
P04	High Pressure Trouble
P05	AC Power Supply Trouble
P13	Alarm Valve Open
P15	Insufficient Gas Level Detected
P16	Compressor Overcurrent Trouble
P22	Outdoor Unit Fan Motor Trouble
P29	Lack of INV compressor wiring, INV compressor actuation failure (including locked), DCCT failure
P31	Group Control Error

Symptoms and Parts to Inspect

Remote controller alarm display	Alarm contents	Judgement conditions	Eliminating condition of alarm	Judgement and correction
P03	Abnormal discharge temperature error • Discharge temp. detected at or above the specified value	Stops when temp. exceeds 103 °C. Alarm output on 5 pre-trips	Recovery at restart	Check refrigerant cycle (gas leak). Check with electronic expansion valve Check discharge temperature sensor (TD).
P05	CT disconnected or AC power supply error DC voltage charge failure	The current value transmitted from the microcomputer on the outdoor unit control substrate is low. When no AC power input for more than 30 seconds to 5 minutes: Single alarm	Recovery at restart	Check outdoor unit control PCB. Lack of reactor wire Check power frequency.
P15	Insufficient gas level detected.	Discharge temperature is 95 °C or higher. Electronic expansion valve is at Step 480. When the above has continued for 1 minute. Indoor air sucking due to body thermostat max (E1 or E2) - TA ≤ 4°C Secondary current ≤ Current value of gas shortage determination	Recovery at restart	1.Check refrigerant cycle (gas leak). 2.Trouble with electronic expansion valve 3.Check outdoor unit valve opening.
L18	4-way valve operation failure • Judged after heating operating for 5 minutes consecutively.	The indoor unit heat exchanger temperature drops even though the compressor is switched on during the heating mode: To +20 °C ≤ C1 Pre-trip 1 time	Recovery at restart	Check 4-way valve. Check 4-way valve wiring. Check outdoor unit control PCB.
P04	High-pressure protection error	High pressure switched ON → OFF (Alarm is output when switch opened.) Pre-trip 4 times.	Recovery at restart	Overload operation of refrigerant cycle
P22	Outdoor unit fan motor trouble • Inverter protection circuit was activated, or lock was detected at outdoor unit fan motor.	Inverter stops after alarm is detected. Pre-trip 10 times	Recovery at restart	1.Position detection trouble. 2.Outdoor unit fan motor overcurrent Protection circuit is activated. • Check outdoor unit control PCB. • See outdoor unit fan judgement methods.
P29	Lack of INV compressor wiring, INV compressor actuation failure, DCCT failure	Inverter stops after alarm is detected. Alarm is output when inverter stops (pre-trip) consecutively 10 times.	Recovery at restart	1.Stops immediately even when operations restarted. • Layer short on the compressor 2.Check HIC circuit. • Wiring trouble
H31	HIC trouble	Pre-trip consecutively 10 times	Temperature dropped	Heat sink and PCB (HIC) • Contact trouble

E04 Error in Indoor Unit Receiving Signal from the Outdoor unit

1. Error Detection Method

When there is no communication within a 3-minute period from the outdoor unit. Or, judged an error when no reply comes from the outdoor unit.

- The outdoor unit is not turned on.
- When the power was turned on after auto address setting was completed, the number of indoor units had been changed.
- · Forgot to turn on the indoor unit.
- The CHK pin and / or TEST pin on the indoor unit's control PC board are shorted.
- Forgot to install the nonvolatile memory (EEPROM) when replacing the indoor unit control PC board.
- Mistakenly set the indoor unit address to Not Set in the remote control's detailed setting mode.
- When indoor unit addresses are duplicated.
- There is a short, open, wrong contact or grounding of the indoor / outdoor control line*.
- There is an error in the receiving circuit on the signal output PC board (optional control PC board).
- · Malfunctions of the outdoor unit
- The thermistor inside the indoor unit is grounded.
- The capacity setting is mismatched between indoor units and the outdoor unit.

1 Power Source	1-1	Is / was the power to the outdoor unit cut off?			r turning the power wait three minutes
Course				· ·	
	4.0	Y		Yes	Power on
	1-2	Is the indoor unit powered off?		No	2-1
2 Indoor / outdoor	2-1	Is the indoor / outdoor wiring connected correctly?	,	Yes	3-1
wiring		is the mass, a satured with g commence contest,		No	Correct the wiring
3 Number	3-1	Was the number of indoor units increased or decreased after	,	Yes	3-2
and setting of indoor	3-1	auto address setting was complete?		No	3-3
units	3-2	Conduct checks prior to auto address setting.			
		Check the indoor unit addresses from the remote control's	,	Yes	3-2
	3-3	detailed settings mode. Is it Not Set (99), or is the indoor unit's address duplicated?		No	3-4
		Check the indoor unit capacity from the remote control's detailed	Yes	4-1	
	3-4	actions made		No	3-2
4 Indoor	4-1	, as and other purchase, or the purchase and other contracts.			Remove the short
unit	board short-circuited?			No	4-2
control PC board	4-2 Is the wireless remote controller connected to on the indoor unit's				4-3
1 0 board	control PC board?				4-5
	4-3	4-3 after several minutes. (When doing so, if two remote controllers are			4-4
	7 0				4-5
	4-4	Replace wireless remote control parts including wiring.			
	4-5	Is the LED on the indoor unit control PC board blinking?			4-6
		13 the EED off the indoor drift control PC board billiking?			4-7
	4-6	The nonvolatile memory (EEPROM) on the indoor unit's control PC improperly installed or the nonvolatile memory is faulty. Correct this nonvolatile memory, write model data to it in the remote control det	s or a	after	replacing the
	4-7	Are all the remote controllers of the other indoor units connected to that outdoor unit displaying F042			or unit both control
				door unit control board	

^{*} indoor / outdoor control line*: Connection cable between outdoor and indoor unit

- Regarding the remote controller check, refer to the Reference Materials.
- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit and / or replacing the indoor unit's control board, refer to the manual that is packaged with the indoor unit service board.

Outdoor Unit Control PCB (CR/HIC)

■ CR-PCB: ACXA73-3552* (U-71PZH3E5)



ĖEPROM

■ CR-PCB : ACXA73-3551* (U-100PZH3E5)



EEPROM

■ CR-PCB : ACXA73-3550* (U-125PZH3E5, U-140PZH3E5)




EEPROM


■ HIC-PCB : ACXA73-3555* (U-71PZH3E5)



■ HIC-PCB : ACXA73-3554* (U-100PZH3E5)



■ HIC-PCB : ACXA73-3553* (U-125PZH3E5, U-140PZH3E5)



5-2-2-3-4


■ CR-PCB : ACXA73-3557* (U-71PZH3E8)




■ CR-PCB : ACXA73-3556* (U-100PZH3E8, U-125PZH3E8, U-140PZH3E8)



■ HIC-PCB : ACXA73-3559* (U-71PZH3E8)



■ HIC-PCB : ACXA73-3558* (U-100PZH3E8, U-125PZH3E8, U-140PZH3E8)






■ ACXA73-3440* : Middle Static Pressure Duct Type



■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E06 Outdoor Unit Failed to Receive Serial Communication Signals from Indoor Unit

(When indoor unit(s) are connected)

1. Error Detection Method

It is judged an error when there is no transmission (reply) from the indoor unit to the outdoor unit for a period of three minutes.

- The indoor unit is not turned on.
- The DISP pin of the indoor unit is shorted.
- There is a short, open, wrong contact or grounding of the indoor / outdoor control line*.
- The signal output control PC board (optional control PC board) inside the indoor unit has failed.
- The thermistor inside the indoor unit is grounded.

1 Indoor unit	1-1	Is the indoor unit powered off?	Yes	Power on
power	1-1	is the indoor drift powered on?		2-1
2 Indoor / outdoor	2-1	Is the indoor / outdoor control line* shorted, opened,		Correct the wiring
wiring		grounded or has a wrong contact?	No	3-1
3 Indoor	3-1	Are the DISP pin and CHK pin on the indoor unit control PC board	Yes	Remove the short
units	3-1	short-circuited?		3-2
PC board	3-2	control PC board? Disconnect the connector mentioned above on the control PC board of the indoor unit control PC board, and see whether the E06 goes off after several minutes. (When doing so, if two remote controllers are	Yes	3-3
			No	3-5
			Yes	3-4
	3-3		No	3-5
	3-4	Replace wireless remote control parts including wiring.		
	3-5	Indoor unit control PC board failure → Replace board.		

- For information on the procedures for replacing the indoor unit's control board, refer to the manual that is packaged with the indoor unit control PCB.
- * indoor / outdoor control line*: Connection cable between outdoor and indoor unit


■ ACXA73-3129* : 4-Way Cassette Type



■ ACXA73-3440* : Middle Static Pressure Duct Type



■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E15 Auto Address Alarm (The total capacity of indoor units is too low.)

1. Error Detection Method

Connecting indoor unit

It is judged an error the total capacity of indoor units replied by communication is lower than that of outdoor unit.

- · The total capacity of indoor units is lower than that of outdoor unit
- · Some indoor unit(s) are connected but power is not turned on
- The CHK pin (CN062 / CN071) and / or TEST pin (CN064) of the indoor unit is shorted when its power is turned on.

2. Error Diagnosis

1 Power	1-1	Is the indoor unit powered off?		Power on
Source		'	No	2-1
2 Indoor / outdoor	0.4	Is the indoor / outdoor wiring connected correctly?	Yes	3-1
wiring	2-1		No	Correct the wiring
3 Number of	3-1	The are removed or made and entering a control of the control of	Yes	3-2
Indoor	3-1		No	4-1
Units	3-2	Conduct checks prior to auto address setting.		
4 Indoor		Do sure that the datailed action items are made at feature action	Yes	4-2
unit control	4-1	Be sure that the detailed setting items are made at factory setting. [U3, F3, K3, T3]	No	Correct the setting Run the auto address
PC board	4-2	process and control and seems and control	Yes	Remove the short
			No	4-3
	4-3		Yes	4-4
			No	4-6
	4-4	Disconnect the connector mentioned above on the control PC board of the indoor unit control PC board and see whether the E15 goes off after several minutes. (When doing so, if two remote controllers are	Yes	4-5
		hairan waad and the cuincless nameth acutuallanis the masic nameth	No	4-6
	4-5	Replace wireless remote control parts including wiring.		
	4.6		Yes	4-7
	4-6	Is the LED blinking on the indoor unit's control PC board?		5-1
	4-7	The nonvolatile memory (EEPROM) on the indoor unit's control board is either not in improperly installed or the nonvolatile memory is faulty. Correct this or after replacing nonvolatile memory, write model data to it in the remote control detailed settings model.		
5 Outdoor unit control PC board	5-1	Check all items under the section "Check Prior to Auto Address Setting".		

· Factory setting

Item code	Item	Value
11	Indoor unit capacity	0
12	System address	99
13	Indoor unit address	99
14	Group control address	99

NOTE

The Item code numbers 11, 12, 13 and 14 can automatically be changed to the appropriate settings from factory settings listed above by making the auto address settings according to the connected outdoor unit capacity and the number of indoor units.

If needed to reset the settings after once changed, return all the item codes to the factory shipment-time settings. It is necessary to set the auto address settings once again.

- For information on the procedures for replacing the nonvolatile memory (EEPROM) of the indoor unit, refer to the manual that is packaged with the indoor unit service board.
- For information on the remote control's detailed settings, see 7-3 and 7-4.
- The alarm also occurs when the indoor unit cannot be recognized (indoor unit only blackout, disconnection of indoor / outdoor control line*, etc.) during auto address setting.

■ ACXA73-3129* : 4-Way Cassette Type




■ ACXA73-3440* : Middle Static Pressure Duct Type



^{*} indoor / outdoor control line* : Connection cable between outdoor and indoor unit

■ ACXA73-3671*: Wall Mounted Type Indoor Unit Control Board



■ ACXA73-3611* : Ceiling Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

■ ACXA73-3565*: 4-Way Cassette 60 × 60 Type Indoor Unit Control Board



TEST pin DISP pin CHK pin RC EEPROM OPTION

E16 Auto Address Alarm (The total capacity of indoor units is too high.)

1. Error Detection Method

It is judged an error the total capacity of indoor units is too high or the total number of indoor units is too many.

- The total capacity of indoor units is too high.
- The total number of indoor units is too many.
- When making group control of the different refrigerant system, the steps to turn on the systems one at a time have not been performed.

1 Auto Address	1-1	Conduct checks prior to auto address setting.
-------------------	-----	---

E20 Auto Address Alarm (No indoor unit connected)

1. Error Detection Method

The outdoor unit detects an error at following cases during auto address setting.

- Indoor unit is not turned on.
- Indoor / outdoor control line* is disconnected and also detects an error in the following cases when the outdoor unit is turned on.
- Address(es) of indoor unit(s) are not assigned correctly.
- Capacity of indoor / outdoor units is mismatched.
- Total number of indoor units is too many.

1 Indoor Unit	1-1	Are the address(es) of indoor unit(s) assigned correctly?		Yes 1-2	
	The the address(es) of mader diff(s) assigned correctly:			No	Set its address
	1-2 Are the indoor units turned on?			Yes	1-3
	1-2	Are the indoor drine turned on:		No	Power on
	Be sure that the indoor and outdoor units are connected with		Yes	1-4	
	1-3			Correct the connection	
	1-4	The indoor / outdoor control line* may be disconnected somewhere between the incommon and the outdoor unit. Make sure the indoor / outdoor control line* is connected.			

^{*} indoor / outdoor control line* : Connection cable between outdoor and indoor unit

F04 Compressor Discharge Temperature Sensor (TD) Trouble

1. Error Detection Method

It is judged an error based on the criteria listed below.

• Open circuit or Short circuit

1 Sensor	1-1	Canada connector in connected to DC heard preparty	Yes	1-2
	1-1	Sensor connector is connected to PC board properly.	No	Reconnect and check
			Yes	Replace sensor
	1-2	Sensor is correctly installed at holder side.	No	Correct and see what happens.
	4.0	Abrahmad tampa aratura ariata arrang after replacing account	Yes	
	1-3	Abnormal temperature exists even after replacing sensor.	No	See what happens.
2 PC board	2-1	Resistance between connector pins on PC board is less than 1 k ohm	Yes	Replace PC board
			No	2-2
	2-2	Abnormal temperature exists even after replacing PC board.	Yes	3-1
			No	See what happens.
3 Operating	3-1	Designated town exeture of outdoor unit is over 40°C	Yes	Correct
status		Peripheral temperature of outdoor unit is over 48°C.	No	3-2
		Tends to have insufficient refrigerant charge in the system.	Yes	Adjust the amount of refrigerant
			No	3-3
	3-3	Check noise.	•	

F06 Inlet Temperature Sensor (C1) in Heat Exchanger Trouble

1. Error Detection Method

• In case of open or short

1 Sensor Trouble	1-1	Is the connector properly connected to PCB?	Yes	
		is the conhecter property conhected to 1 GZ.	No	Reconnect & check
	1-2	Is the resistor between the sockets infinity or 0Ω ?	Yes	Replace sensor.
		is the resistor between the sockets militity of 022?	No	2-1
2 Control PCB Failure	2-1	Outdoor unit control PCB failure Replace PCB with a new one.		

F07 Intermediate Temperature (C2) in Heat Exchanger Trouble

1. Error Detection Method

It is judged an error when open circuit or short circuit.

1 Sensor	1-1	Sensor connector is connected to PC board properly.	Yes	1-2
	1-1	Sensor connector is connected to PC board properly.		Reconnect and check
	1-2	Resistance between sockets is infinity or 0 ohm.	Yes	Replace sensor
	1-2		No	2-1
2 PC board	2-1	Replace PC board because of outdoor control PC board failure.		

F08 Outdoor Air Temperature Sensor (TO) Trouble

1. Error Detection Method

It is judged an error when open circuit or short circuit.

1 Sensor	1 1	1-1 Sensor connector is connected to PC board properly.	Yes	1-2
	1-1 Sensor connector is connected to PC board properly.			Reconnect and check
	1-2 Resistance between sockets is infinity or 0 ohm.		Yes	Replace sensor
	1-2	Resistance between sockets is initially of 0 offin.	No	2-1
2 PC board	2-1	Replace PC board because of outdoor control PC board failure.		

F12 Compressor Inlet Suction Temperature Sensor (TS) Trouble

1. Error Detection Method

It is judged an error when open circuit or short circuit.

1 Sensor	1 1	Conser connector is connected to DC heard properly	Yes	1-2
	1-1	Sensor connector is connected to PC board properly.		Reconnect and check
	1-2	Resistance between sockets is infinity or 0 ohm.	Yes	Replace sensor
	1-2		No	2-1
2 Outdoor control PC board	2-1	Replace PC board because of outdoor control PC board failure.	•	

F31 Outdoor Unit Nonvolatile Memory (EEPROM) Trouble

1. Error Detection Method

It is judged an error based on the criteria listed below.

- When power initially turned ON for the first time, nonvolatile memory (EEPROM) is not installed.
- Read values after writing onto nonvolatile memory (EEPROM) is inconsistent.

1 PC board	1-1	Does EEPROM exist on the control PC board?	Yes	1-2
		Does EEFROW exist off the control FC board?	No	Install EEPROM
	1 2	Is EEPROM installed properly?	Yes	1-3
	1-2	(Check: Bent IC pin or incorrect installation, etc.)	No	Correct
		Incorrect EEPROM Replace with correct EEPROM.		

H01 Primary (input) Overcurrent Detected


1. Error Detection Method

• Primary current effective value detected overcurrent (trip current value).


Туре					PZH3				
Model name (U-)		71PZH3E5	100PZH3E5	125PZH3E5	140PZH3E5	71PZH3E8	100PZH3E8	125PZH3E8	140PZH3E8
value	Heating	21.5A	28.0A	31.0A	32.0A	10.5A	13.0A	14.0A	14.5A
	Cooling	21.5A	28.0A	31.0A	32.0A	10.5A	13.0A	14.0A	14.5A

1 Power	1-1	Not actisfied with ±100/ rated aupply voltage	Yes	Check power supply
supply*	1-1	Not satisfied with ±10% rated supply voltage	No	1-2
	1 2	Extreme voltage fluctuations	Yes	Check power supply
	1-2	Extreme voltage fluctuations	No	1-3
	1_2	Extreme distortion of voltage waveform	Yes	Check power supply
	1-3		No	1-4
	1-4	Instantaneous blackout may sometimes occur.	Yes	Check power supply
	1-4		No	2-1
2 PC board	2-1	Has FUSE 1-A / FUSE 2 and FUSE 3 blown? Check the electrical conduction with tester.	Yes	2-3
wiring	2-1		No	2-2
	2-2	Loose electrical wire connection	Yes	Correct wiring
	2-2	Loose electrical wife confidential	No	2-3
	2-3	Replace CR board.		


^{*} Check not only in the outdoor unit stop mode but in the drive mode.



■ CR-PCB : ACXA73-3551* (U-100PZH3E5)




■ CR-PCB: ACXA73-3550* (U-125PZH3E5, U-140PZH3E5)




5

For 3-Phase Outdoor Unit PCB

■ CR-PCB : ACXA73-3557* (U-71PZH3E8)



■ CR-PCB: ACXA73-3556* (U-100PZH3E8, U-125PZH3E8, U-140PZH3E8)



H02 PAM Trouble (Single-phase only)

1. Error Detection Method

• Error is detected by over-voltage and overcurrent of DC side.

1 Power	1-1	Not satisfied with ±10% rated supply voltage	Yes	Check power supply
supply*	1-1	Not satisfied with ±10% rated supply voltage	No	1-2
	1-2	Extreme voltage fluctuations	Yes	Check power supply
	1-2	Extreme voltage fluctuations	No	1-3
	4.0	Extreme distortion of voltage waveform	Yes	Check power supply
	1-3		No	2-1
2 PC board	2.4	Loose electrical wire connection	Yes	Correct connection
wiring	2-1		No	2-2
	2-2	Replace HIC PC board.		

^{*} Check not only in the outdoor unit stop mode but in the drive mode.

H03 Primary Current CT Sensor (current sensor) Failure

1. Error Detection Method

It is judged an error based on the criteria listed below.

- If 18A or greater is detected when the compressor is stopped (alarm triggered even if the connector is unplugged).
- If no current is detected even though a compressor is running.

2. Error Diagnosis

1 Check the	1-1	Turi the power of again and the outdoor drift.	Yes	Replace CR board.
control PC board			No	See what happens.

• Check also the power supply.

H31 HIC Trouble

1. Error Detection Method

It is judged an error if the computer detects an error signal from the HIC.

An error signal is issued by the HIC if abnormal heat occurs inside the HIC or if there is an overcurrent. However, it is judged an error in the same way if the signal line from the HIC is not connected properly or opened.

- · HIC overcurrent due to HIC fault
- · HIC abnormal heat caused by defective HIC or HIC radiation error
- Signal line is not connected properly or opened between the HIC and the outdoor CR board.

2. Error Diagnosis

1 Wiring	1-1	The willing (power cord and signal line) between the The		1-2
between HIC &	1-1			Correct wiring (connector)
outdoor control PC board	1-2	Everything is normal in the wiring (power cord & signal line) between the HIC and the outdoor CR board. Check the wiring one by one with a tester if there is opened and		2-1
1 0 board		grounding.	No	Replace wiring
2 HIC poor radiation	2-1	good contact with the heat sink (heat dissinating fins) of the		2-2
	2-1	electrical box. Check for looseness in the fastening screws and the condition of the heat-conducting putty.	No	Tighten screw(s), add putty
	2-2	A good flow of cooling air passes through the heat sink (heat dissipating fins) of the electrical box.	Yes	3-1
	2-2	Check for debris blocking the fins.		Remove foreign matter
3 HIC overcurrent	The results of the pass / fail tests for the following HIC board 3-1 IPM show it to be outside the range of the resistance of a		Yes	Replace the HIC PC board
ovorounom.	5-1	1 IPM show it to be outside the range of the resistance of a conforming part.		3-2
	3-2	The inverter compressor was stopped / started more than 10	Yes	Replace the HIC PC board
	J-Z	times and it triggered H31 at a high rate. If alarm code P16 occurs at times, refer to the alarm code P16.		Refer to alarm code P16

HIC board IPM Pass / Fail Tests

- Measure with an analog tester. (Set to the k ohm range)
- Measure the board by itself. (Remove wires connected from other parts.)
- · Measure using IPM terminals.

★ Conforming part resistance value (measure with an analog tester)


Tester terminals									
+		Р			NU				
-	U	V	W	NU	U	V	W	Р	
Resistance value (ohm)	1 k to 5 k	1 k to 5 k	1 k to 5 k	5 k to 10 k	100 k to ∞				
Tester terminals									
-		Р			NU				
+	U	V	W		U	V	W		
Resistance value (ohm)	100 k to ∞	100 k to ∞	100 k to ∞		1 k to 5 k	1 k to 5 k	1 k to 5 k		

• Excepting the parts of "100 k to ∞", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".


Tester terminals								
+	HIC+			HIC-				
-	U	V	W	HIC-	U	V	W	HIC+
Resistance value (ohm)	1 k to 10 k	1 k to 10 k	1 k to 10 k	5 k to 20 k	20 k to ∞ 20 k to ∞		20 k to ∞	20 k to ∞
Tester terminals								
Tester terminals		HIG	C+			F	IIC-	
Tester terminals - +	U	HI0 V	C+		U	V	HIC-	

[•] Excepting the parts of "20 k to ∞ ", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".


■ HIC-PCB : ACXA73-3555* (U-71PZH3E5)




■ HIC-PCB : ACXA73-3554* (U-100PZH3E5)




■ HIC-PCB : ACXA73-3553* (U-125PZH3E5, U-140PZH3E5)





■ HIC-PCB: ACXA73-3558* (U-100PZH3E8, U-125PZH3E8, U-140PZH3E8)



L10 Outdoor Unit Capacity not Set or Invalid

1. Error Detection Method

It is judged an error when outdoor unit capacity not yet setup or systematically unauthorized setting.

1 Check the control PC board	1-1	Was EEPROM replaced when PC board was replaced?	
------------------------------	-----	---	--

L13 Indoor Unit Type Setting Error

1. Error Detection method

• Discordance model(s) between outdoor and indoor units are detected.

1 Discordance		The models for ediabol and indoor arms materied respectively:		2-1
Unit	1-1	(Ex: Are multiple indoor units connected to commercial outdoor units?)	No	Replace indoor units.
2 Installation Failure	Check the indoor unit's motor valve with the remote control detailed settings mode (2C code) and commercial indoor unit is set to "2" and		Yes	3-1
Tallaro		multiple indoor unit is "0".	No	Change installation.
3 Operating Wires for Indoor & Outdoor Units	3-1	Check whether or not indoor and outdoor unit operating wires are shor loose connection or earth fault.	t circ	uit, disconnection,

L18 4-Way Valve Operation Failure

1. Error Detection method

It is judged an error when during heating operation (Comp. ON), the highest detected temperature at an outdoor unit heat exchanger (C1) was 20°C or more above the outdoor air temperature (Air Temp.) continuously for 5 minutes or longer.

1 PC board	1-1	Is the connector wired from the 4-Way valve plugged in the CN-HOT	Yes	1-2
wiring	1-1	or CN-HOT2 connector on the CR PC board properly?	No	Correct connector
	1.0	Lies the 4 May valve wiring become enemal?	Yes	Correct wiring
	1-2	Has the 4-Way valve wiring become opened?	No	1-3
	4.0	Is the wire from the coil for controlling the 4-Way valve firmly	Yes	2-1
	11-3		No	Correct connector
2 4-Way valve	2-1	During heating mode (Comp. ON), insert and remove the connector wired from the 4-Way valve into or from CN-HOT or CN-HOT2		2-2
	2-1	connector on the CR PC board. At the same time, does the ON & OFF sounds occur from the 4-Way valve?	No	Replace CR PC board
	2-2	During heating mode (Comp. ON), does the alarm code L18 reproduce for 5 minutes or longer after insertion and removal of	Yes	2-3
		CN-HOT or CN-HOT2 connector wired from the 4-Way valve connector on the CR PC board?		See what happens
	2-3	The parts inside the 4-Way valve might have fixed at the cooling side. Replace the 4-Way valve		

P03 Compressor Discharge Temperature Trouble

1. Error Detection method

• When the discharge temperature is over 103°C.

1 Adjustment to	1-1	1-1 Not additional refrigerant charged		Additional refrigerant charge
refrigerant			No	2-2
charge	1-2	Tends to have insufficient refrigerant charge in the system.	Yes	Adjust the refrigerant amount
			No	Replace CR board
2 Blockage in	2.1	2-1 Service valve inside the outdoor unit closed	Yes	Open service valve
refrigerant circuit	2-1		No	2-2
Circuit	2-2	Are the tubes clogged?	Yes	Avoid clogging
	2-2		No	2-3
		Is the outdoor unit's electronic control valve operating correctly? (Check for debris clogging the electronic control valve, a problem with the electronical coil and / or the control PC board.)	Yes	2-4
	2-3		No	Replace the electronic control valve
	2-4	Is it observable difference in status of the dew or frost between	Yes	Replace the strainer
	Z-4	the strainer's primary and secondary sides?	No	Replace CR board

P04 High Pressure Trouble

1. Error Detection Method

It is judged an error if the internal circuit of the high pressure switch is dead.

The electronic circuitry of the high pressure switch is cut off if the pressure at the pressure sensor port of the high pressure switch reaches 4.15 MPa. Once it is cut off, it remains cut off until the pressure drops to 3.05 MPa.

- The high pressure switch is malfunctioning.
- · Service valve inside the outdoor unit closed
- There is a short air circuit through the outdoor unit's heat exchanger. (when cooling)
- The outdoor unit's fan is broken. (when cooling)
- The outdoor unit's heat exchanger is clogged. (when cooling)
- There is a short air circuit at the indoor unit. (when heating)
- The filter of the indoor unit is clogged. (when heating)
- The fan of the indoor unit is broken or the fan motor is malfunctioning. (when heating)
- The refrigerant circuit is closed and the high pressure is increasing abnormally high. (solenoid valve or expansion valve not activated, a stuck check valve, etc.)
- · Refrigerant overcharged.
- Nitrogen or air contaminated in the refrigerant system

1 High	The seeket of the high proceure switch is securely inserted in the	Yes	1-2	
pressure switch	1-1	The socket of the high pressure switch is securely inserted in the PC board. The wiring is not opened.	No	Correct connection and / or wiring
	1-2	Even if parts near the high pressure switch are shaken quite a lot, the high pressure cut off will be activated. Even if the covering is in good condition, in several cases vibration	Yes	Replace the high pressure switch (wiring)
		has caused wiring inside to open.	No	2-1
2 Service valve	2-1	Service valve inside the outdoor unit closed	Yes	Open the service valve
			No	2-2
	2-2	There is an extreme difference in temperature in / out of the service	Yes	2-3
	2-2	valve.	No	3-1
	2-3	Check the flare connection, someone may have forgotten to remove If there is a problem within the service valve, replace the valve.	the b	oonnet.
3 Problem	2.4	While cooling is operating an alarm is occurred.		3-2
around the	3-1		No	3-5
heat exchanger	3-2	The intake temperature (ambient temperature) of the outdoor unit's heat exchanger is above 48°C.	Yes	Prevent air short circuit
		Theat exchanger is above 46 C.	No	3-3
	3-3	The outdoor unit's heat exchanger is clogged.	Yes	Clean the heat exchanger
			No	3-4
		Chaple whather the outdoor unit for is normal or if the coalests are	Yes	4-1
	3-4	Check whether the outdoor unit fan is normal or if the sockets are firmly pressed onto the plugs on the outdoor PC board, as well as if any wiring is opened. Are these checking finished without fail?	No	Replace the outdoor unit fan. Correct connection and / or wiring
	3.5	While heating is operating an alarm is occurred	Yes	3-6
	□ 3-5 □ While heating is operating an alarm is occurred		No	1_1

I											
3 Problem around the	3-6	The intake temperature (ambient temperature) of the indoor unit is above 36°C.	Yes	Prevent air short circuit							
heat	above ee e.	No	3-7								
exchanger	3-7	The filter of the indeer unit is alonged	Yes	Clean the filter							
	3-7	The filter of the indoor unit is clogged.	No	3-8							
	3-8	The fan of the indoor unit is broken or the fan motor is faulty.	Yes	Replace the indoor fan (motor)							
			No	4-1							
4 Blockage		le the outdoor unit's electronic control value energing correctly?	Yes	4-3							
in the refrigerant circuit	4-1	Is the outdoor unit's electronic control valve operating correctly? (Check for debris clogging the electronic control valve, a problem with the electronical coil and / or the control PC board.)	No	Repair the electronic control valve of the outdoor unit							
		The indeer unit's expansion valve is energing correctly	Yes	4-3							
	4-2	The indoor unit's expansion valve is operating correctly. (check for debris clogging the valve, a problem with the electronical coil and / or the control PC board)	No	Repair the expansion valve of the indoor unit							
		If an alarm is a surround with the high processor halour 4.45 MDs	Yes	4-4							
	4-3	If an alarm is occurred with the high pressure below 4.15 MPa, with the pressure measured as displayed by the manifold gauge, check the check valve in the compressor discharge line. Are these checking finished without fail?	No	Replace the check valve in the compressor discharge line							
	4-4	The electronic control valve is faulty. In systems where the solenoid valve kits and the ice thermal storage tank are connected, check these solenoid valves.	Yes	Replace the electronic control valve and / or solenoid valve.							
			No	5-1							
5	<i>E</i> 1	From coours when the quotem is energing in cooling made		5-3							
Overcharging	5-1	Error occurs when the system is operating in cooling mode.	No	5-2							
	- 0		Yes	5-4							
	5-2	Error occurs when the system is operating in heating mode.	No	5-5							
	F 0	F 2	F 2	5_3	5-3	5-3	5-3	5-3	An alarm is occurred with the high pressure at 4.15 MPa, with the pressure measured either as displayed by the monitoring software or with a manifold gauge, at which time the temperature of liquid in	Yes	5-5
		the outdoor unit's heat exchanger is detected to be at the temperature of the outside air.	No	Contact the service representative							
		An alarm is occurred with the high pressure at 4.15 MPa, with the pressure measured either as displayed by the monitoring software	Yes	5-5							
	5-4	or with a manifold gauge, at which time the temperature of liquid in the indoor heat exchanger is detected to be at room temperature (intake temperature).	No	Contact the service representative							
	5-5	The system may be overcharged. Check how much refrigerant was a When a system is inspected for airtightness, it is seldom that enough expelled, so some remains in the circuit. In this case, it is necessary to collect the refrigerant and then recharge	nitro	ogen has been							

P05 AC Power Supply Trouble

1. Error Detection Method

- · Instantaneous blackout
- · Zero-cross (waveform input of power supply) error
- DC voltage charge failure


2. Error Diagnosis

Note: The work involved in diagnosing each of the items is extremely dangerous, so turn the power off at the breaker before performing the tests.


1 Check the power	Is the voltage on each of the		Yes	Yes 1-3 : Single-phase model 1-2 : 3-phase model				
supply & the wiring	Check for open circuit a				and the voltage at the breaker. x it and check again.			
	1-2	Power wiring L1 and L2 are conne	octoc	ı	Yes	Correct wiring		
	1 2	Power wiring L1 and L3 are connected.			No	1-3		
	1-3	Turn the power back on and check again.			Yes	2-1		
	1-3	Is the alarm triggered again?	Ū		No	3-1		
2 Check the	2-1	Are the wires (RE1, RE2) from the	e rea	ctor firmly installed?	Yes	2-2		
outdoor	2-1	Are the wires also connected to the		-	No	Correct wiring		
unit HIC PC board	2-2	Turn the power back on and check again.			Yes	Replace the outdoor unit HIC PC board.		
		Is the alarm triggered again?			No	3-1		
3 Final check	3-1	There may be a instantaneous blackout failure. If there is nothing abnormal, see what happens.						

For Single-Phase Outdoor Unit HIC PCB


■ HIC-PCB : ACXA73-3555* (U-71PZH3E5)




■ HIC-PCB : ACXA73-3554* (U-100PZH3E5)




■ HIC-PCB : ACXA73-3553* (U-125PZH3E5, U-140PZH3E5)





■ HIC-PCB: ACXA73-3558* (U-100PZH3E8, U-125PZH3E8, U-140PZH3E8)



P13 Alarm Valve Open

1. Error Detection Method

Detection is performed only in the test run. When once detected or the test run finished without any error, the second detection will not be done.

In case of forgetting to open a valve, P04 (high-pressure switch operational alarm) is occasionally preceded due to the following conditions.

• The status of small temperature change of the operating indoor unit continues for the first 7 minutes since the cooling test run has started.

1 Service valve	1-1	Service valve inside the outdoor unit closed	Yes	Open the service valve
			No	2-1
2 Adjustment to	2-1	-1 Not additional refrigerant charged		Additional refrigerant charge
refrigerant change		That additional formigorant onlyings	No	3-1
3 Blockage	3-1	Are the tubes clogged?	Yes	Avoid clogging
in	3-1		No	3-2
refrigerant circuit		lo the cuttle or unit of a location is control up to an existing control of	Yes	3-3
Circuit	3-2	Is the outdoor unit's electronic control valve operating correctly? (Check for debris clogging the electronic control valve, a problem with the electronical coil and / or the control PC board.)	No	Replace the electronic control valve
	3-3	As the second detection is not done, restart and see what happens	if ther	e is no error.

P15 Insufficient Gas Level Detected

1. Abnormal Detection Method

Alarm occurs in the following cases:

- Compressor's current value shows lower than a certain value.
- Compressor's discharge temperature exceeds 95°C.
- Electronic expansion valve is fully opened.
- The difference between indoor unit heat exchanger temperature and intake temperature is less than 4K.

1 Adjustment of	1-1	Insufficient gas level (Check whether or not pressure level is normal.)	Yes	Recharge with additional refrigerant.
refrigerant amount		(Check whether of not pressure level is normall)	No	1-2
amount	1-2	Check leakage of refrigeration (leak test)	Yes	Replace leaking part with a new one.
				See what happens.

P16 Compressor Overcurrent Trouble

1. Meaning of Alarm

• Secondary current effective value detected the overcurrent (trip current value).

Туре		PZH3									
Model nar	me (U-)	71PZH3E5	100PZH3E5	125PZH3E5	140PZH3E5	71PZH3E8	100PZH3E8	125PZH3E8	140PZH3E8		
	Heating	13.0A	18.0A	19.0A	19.5A	9.0A	11.5A	12.5A	13.0A		
value	Cooling	13.0A	18.0A	19.0A	19.5A	9.0A	11.5A	12.5A	13.0A		

2. Check of content

0 Multiple	0-1	Replaced the compressor (added oil, if it was necessary)	Yes	7-1		
factors	0-1	but it occurred again immediately.	No	-		
	0-2	Replaced the board, but it occurred again immediately.	Yes	Replace compressor along with adding oil, then recheck from 1-1		
			No	-		
1 Power	1-1	Power cord connections are loose.	Yes	Correct the wiring		
Source		Tower cord connections are locate.	No	1-2		
	1-2	Rated power voltage is not within ±10%.	Yes	Test the power supply		
	' -	Trated power voltage is not within ±10%.	No	1-3		
	1-3	Extreme fluctuations in voltage.		Test the power supply		
			_	1-4		
	1-4	An open phase state is observed.		Test the power supply		
		-1 - 1	No	2-1		
2 Board wiring	2-1	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections on the CR board and / or in the		Correct		
		connections of components that are connected by wiring from the CR board.	No	2-2		
	2-2	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of outdoor board(s) that are		Correct		
		connected by wiring from the CR board.	No	2-3		
	2-3	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of outdoor board(s) that are		Correct		
	2-3	connected by wiring from the HIC board.	No	2-4		
	2-4	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of HIC boards connected by		Correct		
	2-4	wiring from the CR board.	No	2-5		
İ	2-5	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of HIC board(s) that are		Correct		
	2-3	connected by wiring from the outdoor board.	No	2-6		
	2-6	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of HIC board(s) that are	Yes	Correct		
	2-0	connected by wiring to a compressor.	No	3-1		

3		Disconnections and / or miswiring are observed in the	Yes	Correct
Compressor	3-1	connecting location of the compressor terminals.	No	
wiring	3-2	Conditions such as burned terminal covers and / or discolored terminals are observed in the connecting location of the compressor terminals.	Yes	Eliminate looseness by changing the terminals, or crimping the terminals again.
			No	4-1
4 Check the	4-1	Outdoor air intake temperature is high.	Yes	Take measures
situation	7 -	Outdoor all intake temperature is high.	No	4-2
	4-2	May be caused by poor outdoor unit air flow		Correct
		(dirty or clogged heat exchanger, blocked discharge port, etc.)	No	
	4-3	Air short circuit has occurred. This is a phenomenon when discharged air (exhaust heat) from the outdoor unit is drawn back	Yes	Prevent air short circuit
		into the suction vent.	No	
	4-4	Indoor air intake temperature is high.		Take measures
			No	
	4-5	The filter of the indoor unit is clogged.		Clean the filter
		Air short sirevit has assumed. This is a phonomorph when	No	Prevent air short
	4-6	Air short circuit has occurred. This is a phenomenon when discharged air (exhaust heat) from the indoor unit is drawn back	Yes	circuit
	. •	into the suction vent.	No	5-1
5 Check	<i>-</i> 1	Descible to energia		5-2
operation	5-1	Possible to operate.	No	6-1
	F 2	Operating pressure is affected by pressure overload.	Yes	5-3
	5-2	Operating pressure is affected by pressure overload.	No	5-4
	5-3			Adjust the amount of refrigerant
			No	5-4
	5-4	5-4 Tends to operate for a long time turning gas back into liquid.		Check the operation of functional parts
			No	5-5
	5-5	5-5 Tends to have insufficient refrigerant charge in the system.		Adjust the amount of refrigerant
			No	5-6
	Even though the high pressure saturation temperature is 48°C or 5-6 less, the secondary current of the inverter is high.		Yes	Replace the compressor
		(The frequency (Hz) ends up dropping due to the current.)		See what happens.
6 Check	6-1	Dividing the outdoor EEPROM INV operation time by the number	Yes	
history		of times oil was supplied to the system yields 3 hours or less.	No	
	6-2	There is a history of H31 in the pre-trip counter of the outdoor EEPROM alarm history.	Yes	Replace the compressor and add oil. However, if 6-1 was "no", it is not necessary to add oil.
			No	7-1
7 Check the HIC boards	7-1	The results of HIC board IPM Pass / Fail Tests show the outside the range of the resistance of a conforming part listed in the next		Replace HIC board
		page.	No	8-1

8 Check the compressor	8-1	The compressor is causing a failure in the insulation.	res	Replace the compressor
			No	8-2
	8-2	The winding resistance of the compressor is abnormal. See "5-3. (3) Coil Resistance of Compressor".	res	Replace the compressor
			No	9-1
9 Check the HIC PC	9-1	Replace the HIC PC board and operate the unit. (Apply putty and		See what happens.
boards		screws must not be loose) Does it operate normally?	No	10-1
10 Check the outdoor unit main PC board	10-1	Replace the control PC board and operate the unit.	See what happens.	

- (Check content of 7) The test check of the HIC board is only a check on the output level, so the input stage may not be working.
- With the filter board broken, alarm P16 may not be triggered.
- HIC board IPM Pass / Fail Tests
 - Measure with an analog tester. (Set to the k ohm range.)
 - Measure the board by itself. (Remove wires connected from other parts.)
 - · Measure using IPM terminals.

★ Conforming part resistance value (measure with an analog tester)


Tester terminals								
+		F)		NU			
-	U	V	W	NU	U	V	W	Р
Resistance value (ohm)	1 k to 5 k	1 k to 5 k	1 k to 5 k	5 k to 10 k	100 k to ∞			
Tester terminals								
-		F)			1	NU	
+	U	V	W		U	V	W	
Resistance value (ohm)	100 k to ∞	100 k to ∞	100 k to ∞		1 k to 5 k	1 k to 5 k	1 k to 5 k	

• Excepting the parts of "100 k to ∞", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".


Tester terminals								
+		HIC	C+		HIC-			
-	U	V	W	HIC-	U	V	W	HIC+
Resistance value (ohm)	1 k to 10 k	1 k to 10 k	1 k to 10 k	5 k to 20 k	20 k to ∞			
Tester terminals								
Tester terminals		HIC	C+			F	IIC-	
	U	HIC	C+ W		U	V	IIC-	

• Excepting the parts of "20 k to ∞ ", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".


■ HIC-PCB : ACXA73-3555* (U-71PZH3E5)



■ HIC-PCB : ACXA73-3554* (U-100PZH3E5)




■ HIC-PCB : ACXA73-3553* (U-125PZH3E5, U-140PZH3E5)




5

■ HIC-PCB : ACXA73-3559* (U-71PZH3E8)



■ HIC-PCB: ACXA73-3558* (U-100PZH3E8, U-125PZH3E8, U-140PZH3E8)



P22 Outdoor Unit Fan Motor Trouble

1. Error Detection Method

• It is judged an error when the outdoor fan motor's rotating signal cannot be detected normally.

1 Wiring		In the connector "CN EM" firmly connected to the outdoor	Yes	2-1		
	1-1	Is the connector "CN-FM" firmly connected to the outdoor control PC board (lock engaged)?	No	Correct the connector connections		
2 Outdoor		Disconnect the connector "CN-FM" from the outdoor control PC	Yes	3-1		
fan motor	2-1	board and rotate the outdoor fan by hand; does it rotate freely? (Check the outdoor fan motor lock)	No	Replace the outdoor fan motor		
3 Outdoor control	3-1	Turn the power on and run the unit again; is P22 triggered again? Or can you see or hear anything that is obviously	Yes	3-2		
PC board		wrong in its rotation?	No	3-3		
	3-2	Replace the outdoor control PC board. (If it fails to operate normal the outdoor control PC board, replace the outdoor fan motor.)	ven after replacing			
	3-3	If there is nothing particularly out of the ordinary, see what happens.				

P29 Lack of INV compressor wiring, INV compressor actuation failure (including locked), DCCT failure

1. Error Detection Method

- Abnormal current is detected at DCCT before start-up.
- Start-up failed during overcurrent and / or step-out detected.
- Open-wire of compressor and / or backspin detected.
- Secondary current is not detected during INV compressor is running.

2. Error Diagnosis

1 Wiring	1-1	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of HIC PC board(s) that are		Correct wiring connections	
		connected by wiring to a compressor. *1	No	1-2	
	1-2	Disconnected parts, miswiring and / or poor connections (loose) are observed in the connections of outdoor board(s) that are	Yes	Correct wiring connections	
		connected by wiring from the HIC PC board. *1	No	2-1	
2	2-1	Disconnections and / or miswiring is observed in the connections	Yes	Correct	
Compressor	2-1	of the compressor terminals. *1	No	2-2	
wiring	2-2	Conditions such as burned terminal covers and / or discolored terminals are observed at the connectors of the compressor terminals. *1		Eliminate looseness by changing the terminals, or crimping the terminals again.	
			No	3-1	
3 Check the HIC PC	3-1	The results of the pass / fail tests for the following HIC PC board IPM show it to be outside the range of the resistance of a		Replace the HIC board	
boards		conforming part.	No	3-2	
	3-2	Replace the HIC PC board and operate the unit. (Apply putty	Yes	See what happens.	
		and screws must not be loose) Does it operate normally?		4-1	
4 Check the outdoor control PC board	4-1	Replace the control PC board and operate the unit.	See	see what happens.	

^{*1} Checking for looseness of compressor terminals by wiggling them has the adverse effect of loosening them, so do not do it.

Evaluate them by discoloration of wire insulation near the terminal.

HIC board IPM Pass / Fail Tests

- Measure with an analog tester. (Set to the k ohm range.)
- Measure the board by itself. (Remove wires connected from other parts.)
- Measure using IPM terminals.

★ Conforming part resistance value (measure with an analog tester)

Tester terminals	ster terminals							
+		F)		NU			
-	U	V	W	NU	U	V	W	Р
Resistance value (ohm)	1 k to 5 k	1 k to 5 k	1 k to 5 k	5 k to 10 k	100 k to	100 k to	100 k to	100 k to
Tester terminals								
-		F)		NU			
+	U	V	W		U	V	W	
Resistance value (ohm)	100 k to	100 k to	100 k to		1 k to 5 k	1 k to 5 k	1 k to 5 k	

• Excepting the parts of "100 k to ∞", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".

Tester terminals								
+		HIG	C+		HIC-			
-	U	V	W	HIC-	U	V	W	HIC+
Resistance value (ohm)	1 k to 10 k	1 k to 10 k	1 k to 10 k	5 k to 20 k	20 k to	20 k to	20 k to	20 k to
Tester terminals								
-		HIG	C+			F	HC-	
+	U	V	W		U	V	W	
Resistance value (ohm)	20 k to	20 k to	20 k to		1 k to 10 k	1 k to 10 k	1 k to 10 k	

 Excepting the parts of "20 k to ∞", it is acceptable if a small resistance value appears as a reference value unless the value is "0 = short-circuit".

P31 Group Control Error


1. Error Detection Method

• Other indoor unit alarms within the group.


1 Other indoor	1 1	Survey the indoor unit that alarms other than "P31" in the indoor unit group and specify the
unit	1-1	causes of failure.

For Single-Phase Outdoor Unit HIC PCB


■ HIC-PCB : ACXA73-3555* (U-71PZH3E5)




■ HIC-PCB : ACXA73-3554* (U-100PZH3E5)




■ HIC-PCB : ACXA73-3553* (U-125PZH3E5, U-140PZH3E5)





■ HIC-PCB: ACXA73-3558* (U-100PZH3E8, U-125PZH3E8, U-140PZH3E8)



5-3. Inspection of Parts (Outdoor Unit)

(1) Electronic control valve (MOV1)

U-25PZ3E5, U-36PZ3E5, U-50PZ3E5, U-60PZ3E5A, U-71PZ3E5A U-36PZH3E5, U-50PZH3E5, U-60PZH3E5

STM / STM1: Measure the voltage between plug pin 5 and pins 1 through 4 at the CN-STM / CN-STM1 connector (white) on the outdoor unit control PCB. (Because of the pulse output, a simplified measurement method is used.

Set the tester to the 12 V range; if the value displayed is approximately 4 V, then the voltage is normal.) If the voltage is normal, measure the resistance between connector pin 5 and pins 1 through 4. Resistance between pin 5 and pins 1 through 4 should be approximately 46 Ω for all. (If the result is 0 Ω or, ∞ then replace the coil.)

U-100PZ3E5, U-125PZ3E5, U-140PZ3E5 U-100PZ3E8, U-125PZ3E8, U-140PZ3E8

MOV1: Measure the voltage between plug pin 5 and pins 1 through 4 at the CN-MOV1 connector (5P, white) on the outdoor unit control PCB. (Because of the pulse output, a simplified measurement method is used. Set the tester to the 12 V range; if the value displayed is approximately 4 V, then the voltage is normal.) If the voltage is normal, measure the resistance between connector pin 5 and pins 1 through 4. Resistance between pin 5 and pins 1 through 4 should be approximately 46 Ω for all. (If the result is 0 Ω or, ∞ then replace the coil.)

U-71PZH3E5, U-100PZH3E5, U-125PZH3E5, U-140PZH3E5 U-71PZH3E8, U-100PZH3E8, U-125PZH3E8, U-140PZH3E8

MOV1: Measure the voltage between plug pin 5 and pins 1 through 4 at the CN-MOV1 connector (5P, white) on the outdoor unit control PCB. (Because of the pulse output, a simplified measurement method is used. Set the tester to the 12 V range; if the value displayed is approximately 4 V, then the voltage is normal.) If the voltage is normal, measure the resistance between connector pin 5 and pins 1 through 4. Resistance between pin 5 and pins 1 through 4 should be approximately 46 Ω for all. (If the result is 0 Ω or, ∞ then replace the coil.)

(2) Outdoor Unit Fan Motor

Model No.	Part No. (Panasonic)	Part No.
U-25PZ3E5	L6CAYYYL0064	NFD-52FV-D840-16
U-36PZ3E5	L6CAYYYL0064	NFD-52FV-D840-16
U-50PZ3E5	L6CAYYYL0064	NFD-52FV-D840-16
U-60PZ3E5	L6CAYYYL0076	NFD-62FV-D840-6
U-71PZ3E5	L6CAYYYL0076	NFD-62FV-D840-6
U-100PZ3E5	L6CBYYYL0302	ZKSP-160-8-1
U-125PZ3E5	L6CBYYYL0302	ZKSP-160-8-1
U-140PZ3E5	L6CBYYYL0302	ZKSP-160-8-1
U-100PZ3E8	L6CBYYYL0302	ZKSP-160-8-1
U-125PZ3E8	L6CBYYYL0302	ZKSP-160-8-1
U-140PZ3E8	L6CBYYYL0302	ZKSP-160-8-1
U-36PZH3E5	L6CAYYYL0076	NFD-62FV-D840-6
U-50PZH3E5	L6CAYYYL0076	NFD-62FV-D840-6
U-60PZH3E5	L6CAYYYL0076	NFD-62FV-D840-6
U-71PZH3E5	L6CBYYYL0283	NFD-71FW-D890-5
U-100PZH3E5	L6CBYYYL0283 L6CBYYYL0284	NFD-71FW-D890-5 NFD-71FW-D890-6
U-125PZH3E5	L6CBYYYL0283 L6CBYYYL0284	NFD-71FW-D890-5 NFD-71FW-D890-6
U-140PZH3E5	L6CBYYYL0283 L6CBYYYL0284	NFD-71FW-D890-5 NFD-71FW-D890-6
U-71PZH3E8	L6CBYYYL0283	NFD-71FW-D890-5
U-100PZH3E8	L6CBYYYL0283 L6CBYYYL0284	NFD-71FW-D890-5 NFD-71FW-D890-6
U-125PZH3E8	L6CBYYYL0283 L6CBYYYL0284	NFD-71FW-D890-5 NFD-71FW-D890-6
U-140PZH3E8	L6CBYYYL0283 L6CBYYYL0284	NFD-71FW-D890-5 NFD-71FW-D890-6

(3) Coil Resistance of Compressor

Madal Na	Part No.	Don't No.	Inverter compressor (at 20°C)			
Model No.	(Panasonic)	Part No.	U - V	V - W	U - W	
U-25PZ3E5	ACXB09-03470	9RS102XFA21	1.211	1.211	1.211	
U-36PZ3E5	ACXB09-03470	9RS102XFA21	1.211	1.211	1.211	
U-50PZ3E5	ACXB09-04960	9RD132XAB21	1.897	1.882	1.907	
U-60PZ3E5	ACXB09-04940	9RD132XAA21	1.897	1.882	1.907	
U-71PZ3E5	ACXB09-04950	9KD240XBA21	0.720	0.708	0.726	
U-100PZ3E5	ACXB09-05130	9VD330XAB21	0.872	0.884	0.859	
U-125PZ3E5	ACXB09-05140	9VD420XAB21	0.659	0.670	0.650	
U-140PZ3E5	ACXB09-05140	9VD420XAB21	0.659	0.670	0.650	
U-100PZ3E8	ACXB09-05180	9VD330XBA21	3.071	3.125	3.031	
U-125PZ3E8	ACXB09-05190	9VD420XBA21	2.510	2.561	2.475	
U-140PZ3E8	ACXB09-05190	9VD420XBA21	2.510	2.561	2.475	
U-36PZH3E5	ACXB09-04940	9RD132XAA21	1.897	1.882	1.907	
U-50PZH3E5	ACXB09-04940	9RD132XAA21	1.897	1.882	1.907	
U-60PZH3E5	ACXB09-04940	9RD132XAA21	1.897	1.882	1.907	
U-71PZH3E5	ACXB09-08270	9RD198XAE21	1.313	1.298	1.308	
U-100PZH3E5	ACXB09-06840	9VD420XAC21	0.659	0.670	0.650	
U-125PZH3E5	ACXB09-06840	9VD420XAC21	0.659	0.670	0.650	
U-140PZH3E5	ACXB09-06840	9VD420XAC21	0.659	0.670	0.650	
U-71PZH3E8	ACXB09-08280	9RD198XBB21	5.176	5.185	5.176	
U-100PZH3E8	ACXB09-06850	9VD420XBB21	2.510	2.561	2.475	
U-125PZH3E8	ACXB09-06850	9VD420XBB21	2.510	2.561	2.475	
U-140PZH3E8	ACXB09-06850	9VD420XBB21	2.510	2.561	2.475	

5-4. How to Replace Fan Motor **Middle Static Pressure Duct Type Removing Fan Motor**


1. Turn off the power supply.

WARNING



ELECTRICAL SHOCK CAN CAUSE SEVERE PERSONAL INJURY OR DEATH.


2. Remove the Lid of electrical component box and the wiring cover. (Screws × 5 locations: Fig. 1) Make sure the PC board should not be electrified. Power supply LED should be lit off on PC board. (Fig. 2)




Lid of electrical component box

Fig. 2

3. Disconnect the interconnector in the middle of the wiring to the fan motor. (Fig. 2)



Power LED



4. Remove the bottom plate. (Fig. 3)




5. Disconnect the wires. (Fig. 4)


Band (cut out) Fig. 4

Band (desorb)


Fig. 3

6. Peel off the tape on the fan casing and remove two screws. (Fig. 6, Fig. 7, Fig. 8) Disconnect four (4) clutches (Fig. 7, Fig. 8) fixing the lower side of the fan casing. Then pull off the fan casing.





- 7. Remove the screws (M5 x 2 locations: Fig. 9) fixing the fan motor. It is recommended that a nutdriver (8mm) be used.
- 8. Remove the bracket and then remove the fan and
- fan motor (Fig. 9).



9. Loosen the fixed screw with a hexagon wrench (3mm, over 100mm in length) and remove the fan (Fig. 10).




Fig. 9

Installing Fan Motor

- 1. For installation, reverse the procedure above.
- 2. Fine tune so that the fan can be positioned in the center of the fan casing.

Fig. 12

Wall Mounted Type Removing Fan Motor



1. Remove 4 screws (4x16) and detach the front grille.

2. Remove the electrical cover.



3. Remove 3 fixing screws from the terminal and ground wires.




4. Remove 1 screw (4×10) and lift the terminal cover.



- 5. Remove the connector.
 - FAN motor


nanoe

 Termistor(Air intake,E1,E2) Louver motor(x2)




6. Remove the air discharge grille.






* Photo shows the right-hand drain.

7. Remove 4 screws (4×16) and detach the electrical component box.




8. Remove 1 screw (4×12).

Disengage the tabs and lift the heat exchanger.



9. Remove the fixing screw of the fan.




10. Disengage the fan shaft.




11. Pull the fan toward the front left side and remove it.



12. Lift the fan motor and remove it.




13. Uninstallation is completed.




Installing Fan Motor

Carry out installation in reverse order to assemble.

Fan installation should be made following the figure below while confirming the position.





Reference

Fan plate and corner of the wall of unit should be in the same position.

NOTE

Noise or damage to the fan can be caused by misalignment of the motor due to its mounting position.

4-Way Cassette 60 × 60 Type Removing Fan Motor

Turn off the power supply.

WARNING



ELECTRICAL SHOCK CAN CAUSE SEVERE PERSONAL INJURY OR DEATH.

- Removing ceiling panel
 - (1) Disconnect the ceiling panel wiring from the terminal board of indoor unit.
 - Remove the 4 screws on the power supply board and remove the cover of the power supply board.



2 Remove the motor connector on the panel.



3 Remove the motor wire from the wiring band.




- (2) Removing ceiling panel from the indoor unit.
 - 4 Remove the 2 screws on the latch of the air intake grille.



(5) Remove the air intake grille fall prevention string.



6 Remove the 4 screws.



(7) Remove the two temporary fixing latches of the panel and remove the panel.





■ Removing Air guider


1) Remove the air intake sensor and nanoe connector.



2 Remove the wiring band on the side of the electrical box and remove the wiring. Use a tool such as a flat-blade screwdriver to loosen the wiring band.








- 3-1 Remove the tape that secures the wiring.
- ③-2 Remove 7 screws.
- ③-3 Remove the sealing material from the "nanoe" air outlet.
 Do not dispose of the sealing material as it needs to be reused during installation. If it is damaged, use service parts described below.
 (Service parts: Parts code / ACXG32-05500)
- 3-4 Remove the air guider.

- Removing Fan Motor
 - (1) With the air guider removed, remove the nut and remove the fan.



- (2)-1 Remove the motor connector.
- 2)-2 Cut the band that fixes the core.



4 Remove the two screws and two claws, and remove the piping fixing parts. *When installing, to confirm that the two claws are fixed.



6 Remove the wiring band. Remove the 2 screws and 3 nuts and remove the motor.





(3) Cut the band that fixes the core and remove the core. Do not dispose the core as it will be reused. If you disposed of it, be sure to arrange service parts. (Service parts: Parts code / J0KF00000067)





5 Remove the motor wiring. Since the sealing material wrapped around the wiring cannot be reused, be sure to arrange service parts and attach them to the replaced motor. (Service parts: Parts code / ACXG32-0570)





5-5. Removing Drain Pan 4-Way Cassette 60 × 60 Type

Turn off the power supply.

WARNING



ELECTRICAL SHOCK CAN CAUSE SEVERE PERSONAL INJURY OR DEATH.

- Removing ceiling panel
 - (1) Disconnect the ceiling panel wiring from the terminal board of indoor unit.
 - Remove the 4 screws on the power supply board and remove the cover of the power supply board.



2 Remove the motor connector on the panel.



3 Remove the motor wire from the wiring band.



- (2) Removing ceiling panel from the indoor unit.
 - 4 Remove the 2 screws on the latch of the air intake grille.



5 Remove the air intake grille fall prevention string.



6 Remove the 4 screws.



(7) Remove the two temporary fixing latches of the panel and remove the panel.





■ Removing Air guider


1) Remove the air intake sensor and nanoe connector.



2 Remove the wiring band on the side of the electrical box and remove the wiring. Use a tool such as a flat-blade screwdriver to loosen the wiring band.







- 3-1 Remove the tape that secures the wiring.
- ③-2 Remove 7 screws.
- ③-3 Remove the sealing material from the "nanoe" air outlet.

Do not dispose of the sealing material as it needs to be reused during installation. If it is damaged, use service parts described below. (Service parts: Parts code / ACXG32-05500)

3-4 Remove the air guider.



1 Remove the rubber cap and drain the drain water.



② Remove the 4 screws and remove the Drain Pan.



5-6. Replacing nanoe unit 4-Way Cassette 60 × 60 Type

Turn off the power supply.

WARNING



ELECTRICAL SHOCK CAN CAUSE SEVERE PERSONAL INJURY OR DEATH.

- Removing ceiling panel
 - (1) Disconnect the ceiling panel wiring from the terminal board of indoor unit.
 - Remove the 4 screws on the power supply board and remove the cover of the power supply board.



2 Remove the motor connector on the panel.



3 Remove the motor wire from the wiring band.




- (2) Removing ceiling panel from the indoor unit.
 - 4 Remove the 2 screws on the latch of the air intake grille.



(5) Remove the air intake grille fall prevention string.



6 Remove the 4 screws.



(7) Remove the two temporary fixing latches of the panel and remove the panel.





■ Replacing nanoe unit

1) Remove the air intake sensor and nanoe connector.




② Remove the wiring band on the side of the electrical box and remove the wiring. Use a tool such as a flat-blade screwdriver to loosen the wiring band.





3 Cut the wiring band.



4 Remove the 3 screws and remove the cover.



- (5) Remove the two claws, two screws and the sealing material, and remove nanoe unit.
 - * When installing, to confirm that the two claws are fixed.
 - ** Do not dispose of the sealing material as it needs to be reused during installation.

If it is damaged, use service parts described below. (Service parts: Parts code / ACXG32-05500)



5-7. How to Replace Receiver PCB of Wireless remote controller CZ-RWRY3 Removing Receiver PCB

1. Turn off the power supply.


WARNING



ELECTRICAL SHOCK CAN CAUSE SEVERE PERSONAL INJURY OR DEATH.


2. Disconnect the RC wiring from the terminal board of indoor unit. (Fig. 5-7-1)

Fig. 5-7-1




3. Remove the screw fixing the corner cover. (Fig. 5-7-2)


Fig. 5-7-2



4. Put your hands into the indentations on the left and right of the ceiling panel and remove the corner cover. (Fig. 5-7-3)


Fig. 5-7-3






5. Remove the cover from the receiver. (Fig. 5-7-4)

Fig. 5-7-4




6. Remove from the claws and take out the Receiver PCB. (Fig. 5-7-5)

Fig. 5-7-5



7. Disconnect the RC wiring and replace the Receiver PCB. (Fig. 5-7-6)

Fig. 5-7-6



8. Return to the installed state by reversing the procedure.